

# BarnettAir

Barnett Investment Group Inc.

Aircraft sales and information  
Phone (256)208-0822 Fax (256)208-8820  
barnettair@gmail.com <http://www.barnettair.com>  
119 North Broadway Avenue, Sylacauga, AL 35150

AdID:174

**2009 Cessna Citation XLS+**

**Serial:560-6012**

**Registration:PP-VYV**



**SUMMARY**

**AIRFRAME**

1010 Hours 450 Cycles

**POWERPLANT**

Pratt & Whitney PW545C

1010 Hours SINCE New by Serial Number: PCE-DF0017

1010 Hours SINCE New by Serial Number: PCE-DF0018

**ADDITIONAL**

450 Cycles Since New Left and Right on 5000 TBO Engines

**MODIFICATIONS****AVIONICS**

This avionics package features a Collins ProLine 21 Avionics Suite with Four 8" x 10" Active Matrix Liquid Crystal Panel Displays. Engine functions are monitored on the Engine Indicating and crew Alerting System.

FLIGHT DIRECTOR / AUTOPILOT: Collins ProLine 21

EFIS: Four Screen EFIS consisting of 2 Primary Flight Displays and 2 Enhanced Multifunction Displays

COMMS: Dual Collins VHF-4000 w/8.33 spacing

NAVS: Dual Collins NAV-4500

DME: Single DME-4000

TRANSPONDERS: Dual Collins TDR-94D Mode S w/Enhanced Surveillance

FMS: Dual Collins FMS-3000 w/Performance Database (WAAS capable)

TCAS II: Collins TCAS-4000 w/change 7

EGPWS: Honeywell Mark V Class A System

RAAS: Runway Awareness and Advisory System

RADAR: Collins TWR-850 Turbulence Doppler System

BROADCAST WEATHER: XM Satellite Weather (displayed on MFD)

ELECTRONIC CHARTS: Jeppesen Charts (displayed on MFD)

HF RADIO: Collins HF-9031A w/SELCAL

CVR: L3 Communications FA 2100

ELT: Artex C406-N

**FEATURES**

Standby Electronic HSI

Standby Airspeed & Altitude Display

Standby Engine Indication System

IFIS with File Server

Engine Chip Detector

Monorail Sunvisor

Executive Writing Tables

Logo Lights

Lead Acid Battery

Externally Serviced Potty

**INTERIOR**

Seating / Layout: 2+9 Center Club Configuration featuring Two Forward-Facing Aft Seats, a Forward Two-Place Divan located across from the entry way, and a Left-Hand, Side-Facing Seat (located across from the Potty) serves as the ninth seat.

Materials / Colors: Seats are covered in regal tan leather; the headliner is heathered satin fabric; the sidewalls are in olive branch fabric; the carpet is multi-colored basket weave; the window reveals are Design Tex, Intrepid; the cabinetry, sideledges and tables are finished in a high-gloss walnut wood veneer; the aft divider has an upper bronze and lower walnut high gloss veneer; the hardware is pewter plated; and the crew seats feature sheepskin covers.

LH Refreshment Center: Includes the master switch panel, heated MAPCO, drip pan, pull-out worksurface, drink storage, storage cabinets, and catering tray storage.

RH Forward Main Storage: Contains coat storage, additional storage with several shelves, and the Rosen 10.4" entertainment display and light switch panel.

Aft Cabin Coat Storage: Located in the lavatory which also includes a water faucet and sink, a faucet light switch, master switch panel, and a trash container.

Additional Storage: Storage for the pilots can be found behind the crew seats and there is a RH Aft Magazine Storage Rack located ahead of the aft divider.

Entertainment System: 10.4" Cabin display with a Rosen Flight View Moving Map.

Phone: AirCell Axxess II with handsets located at the VIP seat (seat 5), seat 8 located behind the VIP seat and the flight deck overhead.

Data outlets are located in the lower sidewall at seats 5 & 8.

Cabin Controls and Outlets

VIP Seat Sideledge: Contains remote cabin temperature and light switches. Additional light switches are located at each individual seat sideledge and the side of the RH storage cabinet for those sitting on the divan. 110 VAC are located at seats 5 and 8. The crew outlet is located at the bottom of the RH chart case

## **EXTERIOR**

This Exterior Features an Overall Snow White base complimented with Green-Gold Metallic, Dark Carmel Metallic, Tropic Green Metallic and Shadow Gray Metallic Stripes

## **HISTORY**

Documents 1, 2, 6, 7, 16, 25, 34, 44, 47 and Engine Minor Inspections complied with by The Orlando Service Center (12/11)

Very High Bulletin Status

## **PRICE**

\$6.950.000

**SPECIFICATIONS AND/OR DESCRIPTIONS ARE PROVIDED AS INTRODUCTORY INFORMATION AND DO NOT CONSTITUTE REPRESENTATIONS OR WARRANTIES OF SELLER OR ITS AGENTS. ACCORDINGLY INSPECTION AND VERIFICATION OF AIRCRAFT AND EQUIPMENT IS THE SOLE RESPONSIBILITY OF THE PURCHASER AND/OR PURCHASERS AGENT. ANY PROPOSED TRANSACTION IS SUBJECT TO FINAL EXECUTION OF A SALES AGREEMENT ACCEPTABLE TO SELLER AND THEIR COUNSEL. AIRCRAFT SUBJECT TO PRIOR SALE OR REMOVAL FROM THE MARKET.**



