



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
050020	RBHA 43 APP. D BRAZILIAN ANNUAL INSPECTION	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		12		22-Jan-2016	1 m 18 d
052500E	INSPECT AIRCRAFT WEIGH	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		36		31-Jan-2018	25 m 27 d
059246	INSPECT INSP DOCUMENT 46	*CF			MTH 21-Jan-2009		O/C			
5-92-01 059201	INSPECTION DOCUMENT 1	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	12 600		31-Dec-2015 1597.3	27 d 482.9
5-92-02 059202	INSPECTION DOCUMENT 2	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	12		31-Dec-2015	27 d
5-92-03 059203	INSPECTION DOCUMENT 3	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	24 1200		31-Dec-2016 2197.3	12 m 27 d 1082.9
5-92-04 059204	INSPECTION DOCUMENT 4	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	24		31-Dec-2016	12 m 27 d
5-92-05 059205	INSPECTION DOCUMENT 5	SBJD			MTH 21-Dec-2012 HRS 690 LDG 421		48 1200		31-Dec-2016 1890	12 m 27 d 775.6
5-92-06 059206	INSPECTION DOCUMENT 6	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-50	36 1800		31-Dec-2017 2797.3	24 m 27 d 1682.9
5-92-07 059207	INSPECTION DOCUMENT 7	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-50	36		31-Dec-2017	24 m 27 d
5-92-08 059208	INSPECTION DOCUMENT 8	SBJD			MTH 21-Dec-2012 HRS 690 LDG 421		48 2400		31-Dec-2016 3090	12 m 27 d 1975.6
5-92-09 059209	INSPECTION DOCUMENT 9	SBJD			MTH 21-Dec-2012 HRS 690 LDG 421		48 1200		31-Dec-2016 1890	12 m 27 d 775.6
5-92-10 059210	INSPECTION DOCUMENT 10	SBJD			MTH 21-Dec-2012 HRS 690 LDG 421		48		31-Dec-2016	12 m 27 d
5-92-11 059211	INSPECTION DOCUMENT 11	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	24		31-Dec-2016	12 m 27 d
5-92-12 059212	INSPECTION DOCUMENT 12	*CF			MTH 21-Jan-2009 HRS 0		3000		3000	1885.6
5-92-13	INSPECTION DOCUMENT 13	KICT			MTH 28-Jan-2014 HRS 856 LDG 523		72			
D291100 059213	DISCARD HYDRAULIC SYSTEM FILTERS: INSPECTION DOCUMENT 13	KICT			MTH 28-Jan-2014 HRS 856 LDG 523		72		31-Jan-2020	49 m 27 d
D324010 059213	DISCARD BRAKE SYSTEMS FILTERS: INSPECTION DOCUMENT 13	KICT			MTH 28-Jan-2014 HRS 856 LDG 523		72		31-Jan-2020	49 m 27 d
5-92-14 059214	INSPECTION DOCUMENT 14	*CF			MTH 21-Jan-2009		96		31-Jan-2017	13 m 27 d



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-92-15 059215	INSPECTION DOCUMENT 15	15 *CF			MTH 21-Jan-2009		144		31-Jan-2021	61 m 27 d
5-92-16 059216	INSPECTION DOCUMENT 16	16 ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	12 400		31-Dec-2015 1397.3	27 d 282.9
5-92-17 059217 : APU	INSPECTION DOCUMENT 17	17 ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604 APUH 260.6	-32	24 500		31-Dec-2016 760.6	12 m 27 d 429.3
5-92-18 059218	INSPECTION DOCUMENT 18	18 ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604 APUH 260.6	-32	24 1000		31-Dec-2016 1260.6	12 m 27 d 929.3
5-92-19 059219	INSPECTION DOCUMENT 19	19 ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	24 2400		31-Dec-2016 3397.3	12 m 27 d 2282.9
5-92-25 059225	INSPECTION DOCUMENT 25	25 KICT			MTH 28-Jan-2014 HRS 856 LDG 523		300		1156	41.6
5-92-26 059226A : APU	INSPECTION DOCUMENT 26	26 *CF			MTH 21-Jan-2009 HRS 0 LDG 0 APUH 0 APUS 0		500			
A801103 APU	DETAILED INSPECTION STARTER/GENERATOR : INSPECTION DOCUMENT 26			300SGL138Q-6 8394XL	MTH 21-Jan-2009 APUH 0		500		500	168.7
5-92-27 059227	INSPECTION DOCUMENT 27	27 SBJD			MTH 21-Dec-2012 HRS 690 LDG 421		600		1290	175.6
5-92-30 059230	INSPECTION DOCUMENT 30	30 *CF			MTH 21-Jan-2009 APUH 0		1000		1000	668.7
5-92-34	INSPECTION DOCUMENT 34	34 ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		6			
B342007 STANDBY 059234	OPERATIONAL CHECK SECURAPLANE BATTERY (ENERGY LEVEL): INSPECTION DOCUMENT 34	34 ICT		100-2410-04 0707080	MTH 22-Jan-2015 HRS 997.3 LDG 604		6		31-Jul-2015	-4 m 4 d
5-92-36	INSPECTION DOCUMENT 36	36 ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24			Over Due
B237006 059236 : CVR	FUNCTIONAL CHECK CVR UNDERWATER LOCATOR BEACON COCKPIT VOICE RECORDER UNDERWATER LOCATING DEVICE (ULD): INSPECTION DOCUMENT 36	36 ICT		DK120 SC43086	MTH 22-Jan-2015 HRS 997.3 LDG 604	-32	24		31-Dec-2016	12 m 27 d
5-92-37	INSPECTION DOCUMENT 37 (NOT CURRENTLY USED)	37 KICT			MTH 28-Jan-2014 HRS 856 LDG 523		36			
5-92-38	INSPECTION DOCUMENT 38	38			MTH 21-Jan-2009		60			
B262005 APU 059238 : APU	RESTORATION (HYDROSTATIC TEST) FIRE BOTTLE : INSPECTION DOCUMENT 38	38 MCO		30100033 52425A1	MTH 30-Apr-2013		60		30-Apr-2018	28 m 26 d



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
B262008 AFT <i>059238 : A</i>	RESTORATION (HYDROSTATIC TEST) ENGINE FIRE BOTTLE : INSPECTION DOCUMENT 38	MCO		30400037-1 60631B1	MTH 30-Apr-2013		60		30-Apr-2018	28 m 26 d
B262008 FORWARD <i>059238 : F</i>	RESTORATION (HYDROSTATIC TEST) ENGINE FIRE BOTTLE : INSPECTION DOCUMENT 38	MCO		30400037-1 60688B1	MTH 30-Apr-2013		60		30-Apr-2018	28 m 26 d
5-92-40 <i>059240</i>	INSPECTION DOCUMENT 40	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-1	36 1200		31-Jan-2018 2197.3	25 m 27 d 1082.9
5-92-41	INSPECTION DOCUMENT 41				MTH 21-Jan-2009		144			
B262004 CABIN <i>059241 : CABIN</i>	RESTORATION (HYDROSTATIC TEST) PORTABLE HALON FIRE EXTINGUISHER : INSPECTION DOCUMENT 41	ICT		C352 X571324	MTH 01-Jan-2008 HRS 1		144		31-Jan-2020	49 m 27 d
B262004 COCKPIT <i>059241 : CKPT</i>	RESTORATION (HYDROSTATIC TEST) PORTABLE HALON FIRE EXTINGUISHER : INSPECTION DOCUMENT 41	ICT		C352 X626085	MTH 01-Jan-2008		144		31-Jan-2020	49 m 27 d
5-92-43	INSPECTION DOCUMENT 43				MTH 21-Jan-2009		A/R			
A324006 LEFT <i>059243 : L</i>	NON DESTRUCTIVE TEST MAIN WHEEL ASSEMBLY : INSPECTION DOCUMENT 43	*CF		3-1571-3 1415	MTH		A/R			
A324006 NOSE <i>059243 : N</i>	NON DESTRUCTIVE TEST WHEEL ASSEMBLY : INSPECTION DOCUMENT 43	KMCO		3-1418-OPT4 8121	MTH 30-May-2014 HRS 911.5 LDG 555		A/R			
A324006 RIGHT <i>059243 : R</i>	NON DESTRUCTIVE TEST MAIN WHEEL ASSEMBLY : INSPECTION DOCUMENT 43	*CF		3-1571-3 3213	MTH 21-Jan-2009		A/R			
5-92-44 <i>059244</i>	INSPECTION DOCUMENT 44 (14 CFR 91.207)	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		12		31-Jan-2016	1 m 27 d
5-92-45	INSPECTION DOCUMENT 45	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24			
B341200 NO. 1 <i>059245 : ADC#1</i>	CALIBRATION TEST (PILOT) AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 45	ICT		822-1109-126 357VK	MTH 22-Jan-2015 HRS 997.3 LDG 604		24		31-Jan-2017	13 m 27 d
B341200 NO. 2 <i>059245 : ADC#2</i>	CALIBRATION TEST (COPILOT) AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 45	ICT		822-1109-126 33H7T	MTH 15-Jan-2015		24		31-Jan-2017	13 m 27 d
B341200 RVSM <i>059245</i>	INSPECT SKIN WAVINESS: INSPECTION DOCUMENT 45	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24		31-Jan-2017	13 m 27 d
B341200 SECONDARY <i>059245 : ADU</i>	CALIBRATION TEST ADU (FAR 91.411) : INSPECTION DOCUMENT 45	ICT		501-1890-08 3155	MTH 15-Jan-2015		24		31-Jan-2017	13 m 27 d
B345307 NO. 1 <i>059245 : XPDR1</i>	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): INSPECTION DOCUMENT 45	ICT		622-9210-008 34JVB	MTH 15-Jan-2015		24		31-Jan-2017	13 m 27 d
B345307 NO. 2 <i>059245 : XPDR2</i>	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): INSPECTION DOCUMENT 45	ICT		622-9210-008 34JVN	MTH 15-Jan-2015		24		31-Jan-2017	13 m 27 d



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-92-47	INSPECTION DOCUMENT 47	SBJD			MTH 11-Jun-2015 HRS 1097.7 LDG 614		3 200			
B243001 059247	FUNCTIONAL CHECK MAIN SHIP (UY006) BATTERY (CAPACITY CHECK) LEAD ACID : INSPECTION DOCUMENT 47	SBJD		RG-380E/44LA5 40708702	MTH 11-Jun-2015 HRS 1097.7 LDG 614		3 200		30-Sep-2015 1297.7	-2 m 4 d 183.3
										Over Due
5-92-48	INSPECTION DOCUMENT 48	KMCO			MTH 30-May-2014 HRS 911.5 LDG 555		500		1411.5	297.1
5-92-50	INSPECTION DOCUMENT 50	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604	-53	6		31-May-2015	-6 m 4 d
										Over Due
5-92-MD 0592MD	INSPECTION DOCUMENT MD	*CF			MTH 21-Jan-2009 HRS 0		120 6000		31-Jan-2019 6000	37 m 27 d 4885.6
5-92-ME 0592ME	INSPECTION DOCUMENT ME	*CF			MTH 21-Jan-2009 HRS 0		15000		15000	13885.6
5-92-MF 0592MF	INSPECTION DOCUMENT MF	*CF			MTH 21-Jan-2009 HRS 0		7500		7500	6385.6
5-92-MJ 0592MJ	INSPECTION DOCUMENT MJ	*CF			MTH 21-Jan-2009 HRS 0		13000		13000	11885.6
5-92-ML 0592ML	INSPECTION DOCUMENT ML	*CF			MTH 21-Jan-2009 HRS 0		11500		11500	10385.6
5-92-MM 0592MM	INSPECTION DOCUMENT MM	*CF			MTH 21-Jan-2009 HRS 0		11000		11000	9885.6
5-92-MN 0592MN	INSPECTION DOCUMENT MN	*CF			MTH 21-Jan-2009 HRS 0		9000		9000	7885.6
5-92-MO 0592MO	INSPECTION DOCUMENT MO	*CF			MTH 21-Jan-2009 HRS 0		12500		12500	11385.6
5-92-MQ	INSPECTION DOCUMENT MQ	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		170		1167.3	52.9
057109 E1	OIL FILTER CHANGE	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24 900		31-Jan-2017 1897.3	13 m 27 d 782.9
057109 E2	OIL FILTER CHANGE	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24 900		31-Jan-2017 1897.3	13 m 27 d 782.9
057120 E1	INSPECTION LOW UTILIZATION	*CF			MTH 21-Jan-2009		120		31-Jan-2019	37 m 27 d
057120 E2	INSPECTION LOW UTILIZATION	*CF			MTH 21-Jan-2009		120		31-Jan-2019	37 m 27 d
057126 E1	INSPECT EEC TLD SYSTEM CHK	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		150		1147.3	32.9
057126 E2	INSPECT EEC TLD SYSTEM CHK	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		150		1147.3	32.9
057159 E1	MINOR INSPECTION	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		12 600		31-Jan-2016 1597.3	1 m 27 d 482.9
057159 E2	MINOR INSPECTION	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		12 600		31-Jan-2016 1597.3	1 m 27 d 482.9

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
A262003 CABIN <i>059213 : CABIN</i>	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)	KICT		C352 X571324	MTH 28-Jan-2014		72		31-Jan-2020	49 m 27 d
A262003 COCKPIT <i>059213 : CKPT</i>	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)	KICT		C352 X626085	MTH 28-Jan-2014		72		31-Jan-2020	49 m 27 d
312001A LEFT HAND	REPLACE BATTERY DIGITAL CLOCK			M877A5V 19551	MTH		13		31-Oct-2015	-1 m 4 d
312001B RIGHT HAND	REPLACE BATTERY DIGITAL CLOCK	ICT		PN SN-UNKNOWN	MTH 22-Jan-2015 HRS 997.3 LDG 604		13		29-Feb-2016	2 m 25 d
B320900 <i>059237 : N2</i>	RESTORATION PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE (HYDROSTATIC TEST)	KICT		40005347-3 5580	MTH 01-Nov-2013		36		30-Nov-2016	11 m 26 d
350000 <i>059237 : O2</i>	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER			804882-14 C07120615	MTH 22-Apr-2013		60		30-Apr-2018	28 m 26 d
054906	REPLACE FUEL NOZZLE ASSEMBLY *CF				21-Jan-2009 APUS 0	1	4000	1	4000	3670
710060 E1	CLEAN/INSPECT ENGINE WIRING HARNESS CONNECTORS AND PERFORMENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESSREPLACEMENT	KICT			MTH 28-Jan-2014 HRS 856 LDG 523		900		1756	641.6
710060 E2	CLEAN/INSPECT ENGINE WIRING HARNESS CONNECTORS AND PERFORMENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESSREPLACEMENT	KICT			MTH 28-Jan-2014 HRS 856 LDG 523		900		1756	641.6
720010 E1	OVERHAUL ENGINE	*CF			MTH 21-Jan-2009 HRS 0		5000		5000	3885.6
720010 E2	OVERHAUL ENGINE	*CF			MTH 21-Jan-2009 HRS 0		5000		5000	3885.6
720030 E1	DOWNLOAD DCU DATA	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		200		1197.3	82.9
720030 E2	DOWNLOAD DCU DATA	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		200		1197.3	82.9
720060 E1	HOT SECTION INSPECTION	*CF			MTH 21-Jan-2009 HRS 0	1	2500	1	2500	1385.6
720060 E2	HOT SECTION INSPECTION	*CF			MTH 21-Jan-2009 HRS 0	1	2500	1	2500	1385.6
731030 E1	INSTALL NEW FUEL FILTER ELEMENT	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24		31-Jan-2017 1897.3	13 m 27 d 782.9
731030 E2	INSTALL NEW FUEL FILTER ELEMENT	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24		31-Jan-2017 1897.3	13 m 27 d 782.9
731100 E1	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24		31-Jan-2017 1897.3	13 m 27 d 782.9

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731100 E2	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		24 900		31-Jan-2017 1897.3	13 m 27 d 782.9
740010 E1	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		600		1597.3	482.9
740010 E2	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	ICT			MTH 22-Jan-2015 HRS 997.3 LDG 604		600		1597.3	482.9
751030 E1	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE	KICT			MTH 28-Jan-2014		-			
751030 E2	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE	KICT			MTH 28-Jan-2014		-			
790020 E1	CHANGE OIL	MCO			MTH 08-Dec-2010 HRS 507.7 LDG 318		O/C			
790020 E2	CHANGE OIL	MCO			MTH 08-Dec-2010 HRS 507.7 LDG 318		O/C			
790030 E1	MONITOR OIL QUALITY				MTH 21-Jan-2009		O/C			
790030 E2	MONITOR OIL QUALITY				MTH 21-Jan-2009		O/C			
790050 E1	ANALYZE OIL	MCO			MTH 07-May-2012 HRS 576 LDG 364		A/R			
790050 E2	ANALYZE OIL	MCO			MTH 07-May-2012 HRS 576 LDG 364		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION FLOW (UY005) VALVE *CF			4713-19 1119	MTH 21-Jan-2009		O/C			
211120 LEFT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 2957	MTH 21-Jan-2009		O/C			
211120 RIGHT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 2948	MTH 21-Jan-2009		O/C			
212100 LOWER LEFT	WARM AIR CHECK VALVE *CF			4001-20 5245A	MTH 21-Jan-2009		O/C			
212100 LOWER RIGHT	WARM AIR CHECK VALVE *CF			4001-20 5249A	MTH 21-Jan-2009		O/C			
212100 UPPER RIGHT	COOL AIR CHECK VALVE *CF			4001-20 5242A	MTH 21-Jan-2009		O/C			
212100 UPPER LEFT	COOL AIR CHECK VALVE *CF			4001-20 5244A	MTH 21-Jan-2009		O/C			
212200	MOTOR AND BLOWER ASSEMBLY *CF			7003-400 0883	MTH 22-Jan-2009		O/C			
213005	MANUAL TOGGLE VALVE 9912409-12	*CF		52773-114 1637	MTH 21-Jan-2009		O/C			
213006	CABIN ALTITUDE (U1005) CONTROLLER 9912409-13	*CF	G	52770-116 2831	MTH 21-Jan-2009		O/C			
213007 PRIMARY	OUTFLOW VALVE 9912409-19	ICT		52771-314 1103B	MTH 22-Jan-2015 HRS 997.3 LDG 604		O/C	0 0		
213007 SECONDARY	OUTFLOW VALVE 9912409-11	MCO		52772-114 1224B	MTH 08-Dec-2010 HRS 507.7 LDG 318		O/C	0 0		
213101	ALT PRESSURE SWITCH 9910095-6	*CF		GB300NA161 0824305	MTH 21-Jan-2009		O/C			
215001	ENVIRONMENTAL CONTROL UNIT 9912493-8	*CF		2215460-3 1149	MTH 21-Jan-2009		O/C			
215004	PAC OVERHEAT SWITCH 1173T0570	ICT		927223-2-2 1093	MTH 10-Dec-2009 HRS 261		O/C	0		
215005	ACM COOLING TURBINE *CF			2206610-1 1150	MTH 21-Jan-2009		O/C			
215006	HEAT EXCHANGER *CF			2340594-6 1193	MTH 21-Jan-2009		O/C			
215100	WATER SPRAY ECU ASPIRATOR 9912493-3	*CF		2215605-1 NSN	MTH 21-Jan-2009		O/C			
215101	WATER SEPARATOR TEMP 1 SENSOR 9914130-20	*CF		1E62-1 3BD29	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
216002	ENVIRONMENTAL TEMP CONTROLLER 9912518-5	*CF	M3	1E64-2 7BD159	MTH 21-Jan-2009		O/C			
216003 NO. 1	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 3BD94	MTH 21-Jan-2009		O/C			
216003 NO. 2	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 9BD385	MTH 21-Jan-2009		O/C			
216009 CABIN	ZONE TEMPERATURE (UC021) SENSOR 9914130-6	*CF		1E46-1 7BD320	MTH 21-Jan-2009		O/C			
216009 COCKPIT	ZONE TEMPERATURE (UF029) SENSOR 9914130-6	*CF		1E46-1 5BD211	MTH 21-Jan-2009		O/C			
216099 216100	ECU TEMP CONTROL VALVE 9912518-2	*CF		27241287-14 9BD365G	MTH 21-Jan-2009		O/C			
216100 LEFT	CABIN TEMPERATURE CONTROL (VT029) VALVE 9912518-2	*CF		27241287-14 8BD347G	MTH 21-Jan-2009		O/C			
216100 RIGHT	COCKPIT TEMPERATURE CONTROL (VT030) VALVE 9912518-2	*CF		27241287-14 7BD293G	MTH 21-Jan-2009		O/C			
216101 LEFT	CABIN DUCT OVERHEAT (SC013) SWITCH 9912518-2	*CF		1173T42 3728	MTH 21-Jan-2009		O/C			
216101 RIGHT	COCKPIT DUCT OVERHEAT (SF034) SWITCH 9912518-2	*CF		1173T42 3750	MTH 21-Jan-2009		O/C			
217001	WATER SEPARATOR 9912493-7	*CF		2341316-2 1143	MTH 21-Jan-2009		O/C			
217101 LEFT	OZONE CONVERTER 9914523-2	*CF		31A437-1 15222631	MTH 21-Jan-2009		O/C			
217101 RIGHT	OZONE CONVERTER 9914523-2	*CF		31A437-1 15232631	MTH 21-Jan-2009		O/C			
221010 AILERON	DRIVE SERVO SVO-3000	SBBR		822-1168-022 3W8KC	MTH 11-Sep-2014 HRS 1019.8 LDG 580		O/C			
221010 ELEVATOR	DRIVE SERVO SVO-3000	KMCO	2	822-1168-022 4HMFY	MTH 30-May-2014 HRS 911.5 LDG 555		O/C	1 0		
221010 RUDDER	DRIVE SERVO SVO-3000	*CF	2	822-1168-022 35BCJ	MTH 21-Jan-2009		O/C			
231003	HIGH FREQUENCY RECEIVER/EXCITER COLLINS HF-9000	*CF	12	822-0101-002 4023	MTH 21-Jan-2009		O/C			
231004A	COUPLER-HF -- HF-9041	*CF	10	622-8114-002 9087	MTH 21-Jan-2009		O/C			
231501	FLITEPHONE VI ASSEMBLY ANTENNA IRIDIUM	*CF		S67-1575-165 4493248	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
232003 NO. 1	COMM ANTENNA	*CF		S65-8282-1 2500	MTH 21-Jan-2009		O/C			
232005 NO. 2	COMM ANTENNA	*CF		21-38-1RF/36 11709	MTH 21-Jan-2009		O/C			
232006 232004A	AIRCELL ROUTER	*CF	K	P12083 1208310466	MTH 21-Jan-2009		O/C			
232009 232009NC	NAV/COMM CONTROL CTL-23D	*CF	1	822-2177-001 352KL	MTH 21-Jan-2009		O/C			
232010 NO. 1	COMM TRANSCEIVER VHF-4000	*CF		822-1468-102 37C2H	MTH 22-Jan-2009		O/C			
232010 NO. 2	COMM TRANSCEIVER VHF-4000	*CF		822-1468-102 37C6M	MTH 22-Jan-2009		O/C			
232021	AIRCELL AXCESS SATELLITE TRANSCEIVER	*CF		P12023 1202311114	MTH 21-Jan-2009		O/C			
235001 NO. 1	AUDIO CONTROL PANEL AMPLIFIER ACP-4130	*CF	A	822-2381-035 353XC	MTH 21-Jan-2009		O/C			
235001 NO. 2	AUDIO CONTROL PANEL AMPLIFIER ACP-4130	*CF	A	822-2381-035 353XD	MTH 21-Jan-2009		O/C			
235005 NO. 1	RADIO INTERFACE UNIT RIU-4110(SELCAL)	*CF		822-1864-072 35CDP	MTH 21-Jan-2009		O/C			
235005 NO. 2	RADIO INTERFACE UNIT RIU-4110	*CF	29	822-1864-022 4V792	MTH 21-Jan-2009		O/C			
237001	COCKPIT VOICE RECORDER FA2100	*CF		2100-1020-02 521468	MTH 21-Jan-2009		O/C			
237004	CVR CONTROL UNIT	*CF	29	S251-1120-00 000482218	MTH 21-Jan-2009		O/C			
237006	CVR UNDERWATER LOCATOR BEACON ICT			DK120 SC43086	MTH 01-Apr-2008		O/C	0		
237006A	CVR UNDERWATER LOCATOR BEACON BATTERY 266-E0305-00	ICT		810-2007/K N/A	MTH 22-Jan-2015 HRS 997.3 LDG 604		DUE DUE DUE DUE	0 0	31-Dec-2020	60 m 27 d
Expiration Date: 31-Dec-2020										
240001 LEFT	POWER CONTROL (UD015) UNIT 9914216-6	*CF		91479-1 2060	MTH 21-Jan-2009		O/C			
240001 RIGHT	POWER CONTROL (UE016) UNIT 9914216-6	*CF		91479-1 2172	MTH 21-Jan-2009		O/C			
242050 LEFT	AC (UD017) GENERATOR 9914435-8	*CF		91372-3 1408B	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
242050 RIGHT	AC (UE018) GENERATOR 9914435-8	*CF		91372-3 1514B	MTH 21-Jan-2009		O/C			
243003 APU	GENERATOR (UT032) CONTROL UNIT	*CF		51525-001F P4617	MTH 21-Jan-2009		O/C			
243003 LEFT	GENERATOR (UT007) CONTROL UNIT	*CF		51525-001F P4499	MTH 21-Jan-2009		O/C			
243003 RIGHT	GENERATOR (UT008) CONTROL UNIT	*CF		51525-001F P3645	MTH 21-Jan-2009		O/C			
243004 LEFT	DC (EI011) AMMETER S3439-1	*CF		MD144-1 H0810031	MTH 21-Jan-2009		O/C			
243004 RIGHT	DC (EI010) AMMETER S3439-1	*CF		MD144-1 J0810140	MTH 21-Jan-2009		O/C			
243005	DC (EI009) VOLTMETER MD129-1	*CF		C662502-0101 L08-10003	MTH 22-Jan-2009		O/C			
243007	MAIN SHIP (UY006) BATTERY S3597-8	ICT		RG-380E/44LA5 40708702	MTH 22-Jan-2015 HRS 997.3 LDG 604		O/C	0 0		
243009	BATTERY TEMP INDICATOR MCO			1229-1 796	MTH 08-Dec-2010 HRS 507.7 LDG 318		O/C	0		
243010	BATTERY TEMP SENSOR	*CF		19504 NSN	MTH 21-Jan-2009		O/C			
243015	BATTERY DISCONNECT (KY001) RELAY	*CF		A876K CR17333	MTH 21-Jan-2009		O/C			
243016	OVERVOLTAGE (UZ003) MONITOR	*CF		1645-1-3 4574	MTH 21-Jan-2009		O/C			
245001	NZ022 DIAGNOSTICS PCB	*CF		6618828-7 0117	MTH 21-Jan-2009		O/C			
245002 LEFT	START NZ013 PCB NZ013	MCO		6618829-14 0302	MTH 07-May-2012 HRS 576 LDG 364		O/C	0 0		
245002 RIGHT	START NZ013 PCB NZ013	MCO		6618829-14 0303	MTH 07-May-2012 HRS 576 LDG 364		O/C	0 0		
245079 LEFT	START CNTL NZ013 PCB	*CF		6318324-5 NSN	MTH 21-Jan-2009		O/C			
245079 RIGHT	START CNTL NZ012 PCB	*CF		6318324-5 NSN	MTH 21-Jan-2009		O/C			
245081	PRESS NZ002 PCB	*CF		6518352-5 NSN	MTH 21-Jan-2009		O/C			
245082	DIMMING NZ023 PCB	*CF		6518366-3 0570	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
245083	PCB-AUDIO CONTROL --	*CF		6618831-11 0113	MTH 21-Jan-2009		O/C			
245086	SQUAT SW NZ006 PCB	*CF		6618706-1 0848	MTH 21-Jan-2009		O/C			
245087	CABIN DOOR NZ007 PCB	*CF		6618823-16 0112	MTH 21-Jan-2009		O/C			
245088	LANDING GEAR CONT NZ009 PCB	*CF		6618822-6 0124	MTH 21-Jan-2009		O/C			
245089	PCB LANDING MONITOR	*CF		6618821-14 0123	MTH 21-Jan-2009		O/C			
245091	NO TAKE-OFF NZ008 PCB	*CF		6618824-6 0117	MTH 21-Jan-2009		O/C			
245092 LEFT	FUEL NZ015 PCB	*CF		6618825-6 0137	MTH 21-Jan-2009		O/C			
245092 RIGHT	FUEL NZ014 PCB	*CF		6618825-6 0135	MTH 21-Jan-2009		O/C			
245094	HYD NZ016 PCB	*CF		6618820-1 0110	MTH 21-Jan-2009		O/C			
245095	POS TAIL NZ017 PCB	*CF		6618827-1 0107	MTH 21-Jan-2009		O/C			
245096 LEFT	ANTI ICE NZ019 PCB	*CF		6618826-1 0123	MTH 21-Jan-2009		O/C			
245096 RIGHT	ANTI-ICE NZ018 PCB	*CF		6618826-1 0120	MTH 21-Jan-2009		O/C			
245098	RUDDER BIAS NZ029 PCB	*CF		6618830-7 0106	MTH 21-Jan-2009		O/C			
245105	TAIL DEICE CONT NZ031 PCB	*CF		6618730-1 0448	MTH 21-Jan-2009		O/C			
245106	TAIL DEICE MON NZ033 PCB	*CF		6618731-1 0451	MTH 21-Jan-2009		O/C			
245107	MISCELLANEOUS NZ035 PCB	*CF		6618832-17 0109	MTH 21-Jan-2009		O/C			
256001 NO. 10	LIFE JACKET	*CF		P01074-207 L241074	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 11	LIFE JACKET --	*CF		P01074-207 L241108	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 1	LIFE JACKET	*CF		P01074-207 L241102	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
256001 NO. 2	LIFE JACKET	*CF		P01074-207 L240936	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 3	LIFE JACKET	*CF		P01074-207 L241109	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 4	LIFE JACKET	*CF		P01074-207 L241223	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 5	LIFE JACKET	*CF		P01074-207 L241049	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 6	LIFE JACKET	*CF		P01074-207 L241057	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 7	LIFE JACKET	*CF		P01074-207 L240955	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 8	LIFE JACKET	*CF		P01074-207 L240980	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256001 NO. 9	LIFE JACKET	*CF		P01074-207 L240956	MTH 01-Jul-2008		120	0	31-Jul-2018	31 m 27 d
256002	EMERGENCY LOCATOR TRANSMITTER C406N	*CF		453-5060 06663	MTH 21-Jan-2009		O/C	0		
256003	EMERGENCY LOCATOR BEACON BATTERY PACK MCO			452-0133 358638-029	MTH 03-May-2013 HRS 724.3 LDG 446		60	0	31-May-2018	29 m 27 d
256004	ELT ANTENNA	*CF		110-340 259411	MTH 21-Jan-2009		O/C			
256011	LIFE RAFT	ICT		RAF1108-103T1 2118DAA	MTH 22-Jan-2015 HRS 997.3 LDG 604		12	0	22-Jan-2016	1 m 18 d
261002 LEFT	ENGINE FIRE DETECT (UT021) CONTROL UNIT 9912036-12	*CF		377-02838 0743606	MTH 21-Jan-2009		O/C			
261002 RIGHT	ENGINE FIRE DETECT (UT020) CONTROL UNIT 9912036-12	*CF		377-02838 0743597	MTH 21-Jan-2009		O/C			
262001 AFT	ENGINE FIRE BOTTLE	*CF		30400037-1 60631B1	MTH 22-Jan-2009		O/C	0		
262001 APU	FIRE BOTTLE 9914513-3	*CF		30100033 52425A1	MTH 21-Jan-2009		O/C	0		
262001 FORWARD	ENGINE FIRE BOTTLE	*CF		30400037-1 60688B1	MTH 22-Jan-2009		O/C	0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER KICT			C352 X571324	MTH 28-Jan-2014 HRS 856 LDG 523		O/C			
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER KICT			C352 X626085	MTH 28-Jan-2014 HRS 856 LDG 523		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
263004 262003 : APU	APU FIRE BOTTLE CARTRIDGE	ICT		13083-5 EDJ14H543-001	MTH 22-Jan-2015 HRS 997.3 LDG 604		72		31-Aug-2020	56 m 27 d
Manufacture Date: 31-Aug-2014										
263006 262003 : FL	FORWARD ENGINE BOTTLE FORWARD CARTRIDGE	SBJD		13083-5 N/A	MTH 30-Apr-2014 HRS 941.9 LDG 536		72	1	31-Mar-2020	51 m 27 d
263008 262003 : FR	FORWARD ENGINE BOTTLE AFT CARTRIDGE	SBJD		13083-5 N/A	MTH 30-Apr-2014 HRS 941.9 LDG 536		72	1	31-Mar-2020	51 m 27 d
263010 262003 : AL	AFT ENGINE BOTTLE FORWARD CARTRIDGE	SBJD		13083-5 N/A	MTH 30-Apr-2014 HRS 941.9 LDG 536		72	1	31-Mar-2020	51 m 27 d
263012 262003 : AR	AFT ENGINE BOTTLE AFT CARTRIDGE	SBJD		13083-5 N/A	MTH 30-Apr-2014 HRS 941.9 LDG 536		72	1	31-Mar-2020	51 m 27 d
272001	RUDDER BIAS SHUTOFF VALVE *CF			5307-1 1504C	MTH 21-Jan-2009		O/C			
272002 LEFT	STICK SHAKER (MC001) UNIT *CF	A		201 8281	MTH 21-Jan-2009		O/C			
272002 RIGHT	STICK SHAKER (MF004) UNIT *CF	A		201 8307	MTH 21-Jan-2009		O/C			
272003	RUDDER BIAS ACTUATOR *CF			6660613-12 NSN	MTH 21-Jan-2009		O/C			
273020	AFT ELEVATOR TRIM CABLE ASSEMBLY			PN SN-UNKNOWN	MTH 21-Jan-2009 HRS 0		4800	0	4800	3685.6
274000	HORIZONTAL STABILIZER ACTUATOR 9912548-7	MCO		41011680-108 0280	MTH 29-Jul-2009 HRS 136		O/C	0		
274001	HYDRAULIC MANIFOLD ASSEMBLY 9912625-19	*CF		8244-2 0368	MTH 21-Jan-2009		O/C			
274013	HORIZONTAL STABILIZER ISOLATION (UY015) VALVE 9912625-13	*CF		4220-1 0378	MTH 21-Jan-2009		O/C			
274044	HORIZONTAL STAB VALVE ASSY 9912625-12	*CF		4218-1 0379	MTH 21-Jan-2009		O/C			
275001	FLAP CONTROL (UY024) VALVE 9912625-5	*CF		4216-3 0381	MTH 21-Jan-2009		O/C			
275003 LEFT	FLAP ACTUATOR 9912007-2	*CF		1535000-3 3114	MTH 21-Jan-2009		O/C			
275003 RIGHT	FLAP ACTUATOR 9912007-2	*CF		1535000-3 3062	MTH 21-Jan-2009		O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 LEFT WING LEFT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 LEFT WING LEFT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 LEFT WING RIGHT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 LEFT WING RIGHT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 RIGHT WING LEFT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 RIGHT WING LEFT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 RIGHT WING RIGHT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
275005 RIGHT WING RIGHT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 NSN	MTH 21-Jan-2009 LDG 0		5000	0	5000	4373
276001 LEFT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 3411	MTH 21-Jan-2009		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 3434	MTH 21-Jan-2009		O/C			
276002	SPEED BRAKE CONTROL VALVE 9912625-6	*CF		4216-2 0375	MTH 21-Jan-2009		O/C			
276003	SPEED BRAKE SAFETY VALVE 9912625-7	*CF		4217-1 0388	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
280003 LEFT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 5574XP	MTH 21-Jan-2009		O/C			
280003 RIGHT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 5331XP	MTH 21-Jan-2009		O/C			
280004 LEFT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 5287	MTH 21-Jan-2009		O/C			
280004 RIGHT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 5368	MTH 21-Jan-2009		O/C			
281101 LEFT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 2008	MTH 21-Jan-2009		O/C			
281101 RIGHT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 2025	MTH 21-Jan-2009		O/C			
282011 LEFT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4529	MTH 21-Jan-2009		O/C			
282011 LEFT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4601	MTH 21-Jan-2009		O/C			
282011 LEFT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4375	MTH 21-Jan-2009		O/C			
282011 RIGHT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4532	MTH 21-Jan-2009		O/C			
282011 RIGHT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4609	MTH 21-Jan-2009		O/C			
282011 RIGHT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4610	MTH 21-Jan-2009		O/C			
282012 LEFT <i>282012A : L</i>	FUEL BOOST CARTRIDGE	*CF		LR55505-2 D1668	MTH 21-Jan-2009		O/C			
282012 LEFT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF		LR55540B B1594	MTH 21-Jan-2009		O/C			
282012 RIGHT <i>282012A : R</i>	FUEL BOOST CARTRIDGE	*CF		LR55505-2 D1667	MTH 21-Jan-2009		O/C			
282012 RIGHT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF		LR55540B B1593	MTH 21-Jan-2009		O/C			
282013 LEFT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 1539	MTH 21-Jan-2009		O/C			
282013 RIGHT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 1563	MTH 21-Jan-2009		O/C			
282014	FUEL CROSSFEED ACTUATOR 9914423-2	SMF		MA20A1029-1 AA338705	MTH 12-Jul-2013 HRS 769 LDG 475		O/C	0 0 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
282100 LEFT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE	*CF		80002-101 2135	MTH 21-Jan-2009		O/C			
282100 RIGHT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE	*CF		80002-101 2136	MTH 21-Jan-2009		O/C			
282106	FUEL CROSSFEED VALVE 9914423-4	*CF		125838AW AA171418	MTH 21-Jan-2009		O/C			
282108 LEFT	MOTIVE FLOW SHUTOFF (UY009) VALVE	*CF		4151 1573	MTH 21-Jan-2009		O/C			
282108 RIGHT	MOTIVE FLOW SHUTOFF (UY008) VALVE	*CF		4151 1596	MTH 21-Jan-2009		O/C			
282118 LEFT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 AA130454	MTH 21-Jan-2009		O/C			
282118 RIGHT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 AA145289	MTH 21-Jan-2009		O/C			
282200 LEFT	LOW LEVEL VALVE ASSY	*CF		726400-1 1493	MTH 21-Jan-2009		O/C			
282200 RIGHT	LOW LEVEL VALVE ASSY	*CF		726400-1 1439	MTH 21-Jan-2009		O/C			
282201	VALVE-REFUEL/DEFUEL	*CF		9036-351-2 1616	MTH 21-Jan-2009		O/C			
282202 LEFT	FUEL VALVE ASSY	*CF		750800-2 1587	MTH 21-Jan-2009		O/C			
282202 RIGHT	FUEL VALVE ASSY	*CF		750800-2 1539	MTH 21-Jan-2009		O/C			
284012 LEFT	LOW FUEL LEVEL SENSOR 9914427-2	*CF		GIF5400-43 2935	MTH 21-Jan-2009		O/C			
284012 RIGHT	LOW FUEL LEVEL SENSOR 9914427-2	*CF		GIF5400-43 2947	MTH 21-Jan-2009		O/C			
284013 LEFT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 MN20224	MTH 21-Jan-2009		O/C			
284013 RIGHT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 MN20777	MTH 21-Jan-2009		O/C			
284014 LEFT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 MN18444	MTH 21-Jan-2009		O/C			
284014 RIGHT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 MN18442	MTH 21-Jan-2009		O/C			
284015 LEFT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 MN19278	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284015 RIGHT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 MN18930	MTH 21-Jan-2009		O/C			
284016 LEFT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 MN16394	MTH 21-Jan-2009		O/C			
284016 RIGHT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 MN20205	MTH 21-Jan-2009		O/C			
284017 LEFT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 MN18458	MTH 21-Jan-2009		O/C			
284017 RIGHT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 MN19936	MTH 21-Jan-2009		O/C			
284018 LEFT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 MN16356	MTH 21-Jan-2009		O/C			
284018 RIGHT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 MN20177	MTH 21-Jan-2009		O/C			
284019 LEFT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 MN18587	MTH 21-Jan-2009		O/C			
284019 RIGHT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 MN20213	MTH 21-Jan-2009		O/C			
284196	FUEL QUANTITY SIGNAL CONDITIONER 9912498-9	*CF		10635B03Y04 08091509	MTH 21-Jan-2009		O/C			
291001	HYDRAULIC RESERVOIR 9912542-2	*CF		7470-1 0133	MTH 21-Jan-2009		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 5880	MTH 21-Jan-2009		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 5862	MTH 21-Jan-2009		O/C			
291005 LEFT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 07344	MTH 21-Jan-2009		O/C			
291005 RIGHT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 07410	MTH 21-Jan-2009		O/C			
291008	SPEED BRAKE THERMAL RELIEF VALVE 9912625-8	*CF		2664 0366	MTH 21-Jan-2009		O/C			
291010	HYD PRESS SWITCH 9912625-3	*CF		80637 1187	MTH 21-Jan-2009		O/C			
291013 LEFT	FIREWALL HYD SHUTOFF VALVE 9912625-3	*CF		AV24B1325C5 AA159696	MTH 21-Jan-2009		O/C			
291013 RIGHT	FIREWALL HYD SHUTOFF VALVE 9912625-3	*CF		AV24B1325C5 AA157240	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301001 LEFT WING	ANTI-ICE BLEED AIR UNDER TEMP SL013 SWITCH	*CF		1173T42-4 4159	MTH 22-Jan-2009		O/C			
301001 RIGHT WING	ANTI-ICE BLEED AIR UNDER TEMP SR016 SWITCH	*CF		1173T42-4 4095	MTH 21-Jan-2009		O/C			
301002	ISOLATION VALVE 9912403-2	*CF		2602-36 1810	MTH 21-Jan-2009		O/C			
301008 LEFT	DEICE TAIL VALVE	*CF		3D2353-06 N084360	MTH 21-Jan-2009		O/C			
301008 RIGHT	DEICE TAIL VALVE	*CF		3D2353-06 N084346	MTH 21-Jan-2009		O/C			
301020	WINDSHIELD RAIN REMOVAL MN001 FAN	*CF		011598-501 C08170038	MTH 21-Jan-2009		O/C			
301137 LEFT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VD001 VALVE	MCO		1962-00-7 2666	MTH 08-Dec-2010 HRS 507.7 LDG 318		O/C	8 0		
301137 RIGHT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VE002 VALVE	*CF		1962-00-7 4676	MTH 21-Jan-2009		O/C			
301201 LEFT	TAIL DEICE PRESSURE SV005 SWITCH	*CF		1106P55-1 6573A	MTH 21-Jan-2009		O/C			
301201 RIGHT	TAIL DEICE PRESSURE SV004 SWITCH	*CF		1106P55-1 6540A	MTH 21-Jan-2009		O/C			
301202 LEFT	HORIZ STAB DEICE BOOT	*CF		P29S4D5280-11 MAPL850	MTH 21-Jan-2009		O/C			
301202 RIGHT	HORIZ STAB DEICE BOOT	*CF		P29S4D5280-12 MAQD430	MTH 22-Jan-2009		O/C			
302101 LEFT	PRESSURE REG VALVE 9912495-4	*CF		1946-00-19 4708	MTH 21-Jan-2009		O/C			
302101 RIGHT	PRESSURE REG VALVE 9912495-4	*CF		1946-00-19 4711	MTH 21-Jan-2009		O/C			
302104 LEFT	NACELLE INLET SWITCH	*CF		1173T0759 5068	MTH 21-Jan-2009		O/C			
302104 RIGHT	NACELLE INLET SWITCH	*CF		1173T0759 5007	MTH 21-Jan-2009		O/C			
303001 LEFT	PITOT TUBE	*CF		PH1100-1-VCW 1015803	MTH 22-Jan-2009		O/C			
303001 RIGHT	PITOT TUBE	*CF		PH1100-1-VCW 1015801	MTH 22-Jan-2009		O/C			
303001 STANDBY	PITOT TUBE	*CF		PH1100-1-RCDW 1048209	MTH 22-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
304100 LEFT	WINDSHIELD CONTROLLER 9914411-2	*CF		856-1-3 208250025	MTH 21-Jan-2009		O/C			
304100 RIGHT	WINDSHIELD CONTROLLER 9914411-2	*CF		856-1-3 208250020	MTH 21-Jan-2009		O/C			
720080 E1	ANTI-ICING VALVE 31J2879-05	*CF		540-0406-5 4540	MTH 21-Jan-2009		O/C			
720080 E2	ANTI-ICING VALVE 31J2879-05	*CF		540-0406-5 4538	MTH 21-Jan-2009		O/C			
312001 LEFT HAND	DIGITAL CLOCK	*CF		M877A5V 19551	MTH 21-Jan-2009		O/C			
312002I	INCLINOMETER	*CF		N55DMG2RXA 08072424	MTH 21-Jan-2009		O/C			
313003 LEFT	ENGINE ACCELEROMETER	*CF		6222SM15 21721	MTH 21-Jan-2009		O/C			
313003 RIGHT	ENGINE ACCELEROMETER	*CF		6222SM15 21743	MTH 21-Jan-2009		O/C			
316001	TILT INDICATOR	*CF		3001J72 24251	MTH 21-Jan-2009		O/C			
321003 LEFT MAIN LANDING GEAR	TRUNNION	*CF		6641630-27 NSN	MTH 21-Jan-2009 LDG 0		33300	0	33300	32673
321003 RIGHT MAIN LANDING GEAR	TRUNNION	*CF		6641630-28 NSN	MTH 21-Jan-2009 LDG 0		33300	0	33300	32673
321004 LEFT MAIN LANDING GEAR	TRAILING LINK	*CF		6641530-1 169	MTH 21-Jan-2009 LDG 0		33300	0	33300	32673
321004 RIGHT MAIN LANDING GEAR	TRAILING LINK	*CF		6641530-2 170	MTH 21-Jan-2009 LDG 0		33300	0	33300	32673
321011 LEFT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 NSN	MTH 21-Jan-2009 LDG 0		33300	0	33300	32673
321011 RIGHT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 NSN	MTH 21-Jan-2009 LDG 0		33300	0	33300	32673
321020 LEFT MAIN LANDING GEAR	BREATHER VENT	ICT		QSB-5-SS N/A	MTH 22-Jan-2015 HRS 997.3 LDG 604		12 600	0 0	31-Jan-2016 1597.3	1 m 27 d 482.9
321020 RIGHT MAIN LANDING GEAR	BREATHER VENT	ICT		QSB-5-SS N/A	MTH 22-Jan-2015 HRS 997.3 LDG 604		12 600	0 0	31-Jan-2016 1597.3	1 m 27 d 482.9
321020A LEFT MAIN LANDING GEAR	NON REMOVABLE VENT --	*CF		NON REMOVABLE BREATH VENT NSN	MTH 21-Jan-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
322001 NOSE	LANDING GEAR ASSEMBLY	*CF		6642625-8 77	MTH 21-Jan-2009 LDG 0		33300	0	33300	32673
322002 NOSE GEAR	SHIMMY DAMPER	*CF		5543001-11 1150	MTH 21-Jan-2009		O/C			
322007 NOSE GEAR	TRUNNION	*CF		6642611-9 NSN	MTH 21-Jan-2009		O/C			
323001 LEFT MAIN LANDING GEAR	ACTUATOR 9912537-3	*CF		1550000-5 1571	MTH 21-Jan-2009 LDG 0		70200	0	70200	69573
323001 RIGHT MAIN LANDING GEAR	ACTUATOR 9912537-4	*CF		1550000-6 1576	MTH 21-Jan-2009 LDG 0		70200	0	70200	69573
<i>323002 : R</i>										
323003 NOSE LANDING GEAR	ACTUATOR 9912491-5	*CF		1549300-9 0872	MTH 22-Jan-2009 LDG 5		33300	0	33305	32678
323004 LEFT	UPLOCK ACTUATOR	*CF		5527504-3 4321	MTH 21-Jan-2009		O/C			
323004 NOSE	UPLOCK ACTUATOR	*CF		5527504-3 4314	MTH 21-Jan-2009		O/C			
323004 RIGHT	UPLOCK ACTUATOR	*CF		5527504-3 4345	MTH 21-Jan-2009		O/C			
323005	PRESSURE EMER GEAR GAUGE	*CF		19940929-1 027918	MTH 21-Jan-2009		O/C			
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	KICT		40005347-3 5580	MTH 28-Jan-2014 HRS 856 LDG 523		288		31-Aug-2031	188 m 27 d
Manufacture Date: 01-Aug-2007										
323007	LANDING GEAR CONTROL (VY047) VALVE	*CF		4219-1 0376	MTH 21-Jan-2009		O/C			
323008	DUMP VALVE	*CF		9615 0381	MTH 21-Jan-2009		O/C			
323009	LANDING GEAR CONTROL	*CF	A	049801-001 N5948	MTH 21-Jan-2009		O/C			
323010 LEFT MAIN LANDING GEAR	OLEO ASSEMBLY	*CF		6641615-6 827	MTH 21-Jan-2009 LDG 0		38000	0	38000	37373
323010 RIGHT MAIN LANDING GEAR	OLEO ASSEMBLY	*CF		6641615-6 825	MTH 21-Jan-2009 LDG 0		38000	0	38000	37373
323011 LEFT MAIN LANDING GEAR	OLEO UPPER CAP	*CF		6641616-4 NSN	MTH 21-Jan-2009 LDG 0		14900	0	14900	14273
323011 RIGHT MAIN LANDING GEAR	OLEO UPPER CAP	*CF		6641616-4 NSN	MTH 21-Jan-2009 LDG 0		14900	0	14900	14273



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
323014 323010A	LOADING VALVE 9912625-18	*CF		4215-2 0246	MTH 21-Jan-2009		O/C			
324001 LEFT	MAIN WHEEL ASSEMBLY 9912487-10	CR9		3-1571-3 1415	MTH 15-Apr-2010 HRS 352.3 LDG 216		O/C	0 0 0		
324001 RIGHT	MAIN WHEEL ASSEMBLY 9912487-10	CRG		3-1571-3 3213	MTH 09-Sep-2009 HRS 176.3 LDG 108		O/C	108		
324002 NOSE	WHEEL ASSEMBLY 9914069-4	KMCO		3-1418-OPT4 8121	MTH 30-May-2014 HRS 911.5 LDG 555		O/C	0 0 0		
324003 LEFT	MAIN BRAKE ASSEMBLY 9912487-7	*CF		2-1601-1 1675	MTH 21-Jan-2009		O/C			
324004 RIGHT	MAIN BRAKE ASSEMBLY 9912487-7	*CF		2-1601-1 1769	MTH 21-Jan-2009		O/C			
324005 LEFT	MAIN TIRE 9912488-3	KICT		M13702 3271S143	MTH 28-Jan-2014 HRS 856 LDG 523		O/C	0 0 0		
324005 RIGHT	MAIN TIRE 9912488-3	MCO		M13702 1326S087	MTH 07-May-2012 HRS 576 LDG 364		O/C	0 0 0		
324006	NOSE TIRE 9914070-1	KMCO		031-613-8 3340S00270	MTH 30-May-2014 HRS 911.5 LDG 555		O/C	6 0 0		
324009	POWER BRAKE VALVE 9912627-6	*CF		32-105-3 509	MTH 21-Jan-2009		O/C			
324010 LEFT	EXTEND/RETRACT VALVE 9912627-6	*CF		98120 4104A	MTH 21-Jan-2009		O/C			
324010 NOSE	EXTEND/RETRACT VALVE 9912627-6	*CF		98120 4513A	MTH 21-Jan-2009		O/C			
324010 RIGHT	EXTEND/RETRACT VALVE 9912627-6	*CF		98120 4269A	MTH 21-Jan-2009		O/C			
324014	EMERGENCY AIR BRAKE CONTROL VALVE 9912627-6	*CF		65830-4 1107	MTH 21-Jan-2009		O/C			
324015 LEFT	BRAKE SHUTTLE VALVE 9912627-6	*CF		211-114 1791	MTH 21-Jan-2009		O/C			
324015 RIGHT	BRAKE SHUTTLE VALVE 9912627-6	*CF		211-114 1887	MTH 21-Jan-2009		O/C			
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-3	*CF		640931 6850	MTH 21-Jan-2009		O/C			
324020	ANTISKID CONTROL (UY009) VALVE 9912489-4	*CF		39-837 1081	MTH 21-Jan-2009		O/C			
324022	ANTISKID DIGITAL CONTROL 9912489-9	*CF		42-985-2 855A	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324023	POWER BRAKE ACCUMULATOR 9912644-1	*CF		7551-1 0295	MTH 21-Jan-2009		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 NSN	MTH 21-Jan-2009		O/C			
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 NSN	MTH 21-Jan-2009		O/C			
324025	PRESSURE (SN011) SWITCH *CF			GPP1250-52 0833103	MTH 21-Jan-2009		O/C			
324026	POWER PACK MOTOR *CF			MP50B1 4020	MTH 21-Jan-2009		O/C			
324027	ANTISKID FAULT DISPLAY 9912305-9	*CF		42-92750 2375A	MTH 21-Jan-2009		O/C			
324101	PARKING BRAKE VALVE 9912388-11	*CF		98433-2 0302	MTH 21-Jan-2009		O/C			
324153 3242153	PRESS ANTISKID BRK SWITCH *CF			GPP1250-73 0750710	MTH 22-Jan-2009		O/C			
324200 324201	ANTISKID PRESSURE GAUGE *CF			19940929-1 028258	MTH 21-Jan-2009		O/C			
324206	ANTISKID HYD RELIEF VALVE *CF			1785-2 999	MTH 21-Jan-2009		O/C			
326005 LEFT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 NSN	MTH 21-Jan-2009		O/C			
326005 RIGHT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 NSN	MTH 21-Jan-2009		O/C			
326005	NOSE GEAR UP & LOCKED (SN001) SWITCH *CF			65-430087 NSN	MTH 21-Jan-2009		O/C			
331001 CENTER	5 VDC UN004 DIMMER POWER SUPPLY *CF			273-1 207420003	MTH 21-Jan-2009		O/C			
331001 LEFT	5 VDC UN002 DIMMER POWER SUPPLY *CF			273-1 207420003	MTH 21-Jan-2009		O/C			
331011	EL PANEL INVERTER *CF			EM2044-1 6153A	MTH 21-Jan-2009		O/C			
334001	PULSE LITE CONTROL *CF			2401C TR01677	MTH 21-Jan-2009		O/C			
334002	EMPENNAGE LIGHT ASSY *CF			01-0790044-37 NSN	MTH 21-Jan-2009		O/C			
334003	TAIL LIGHT ASSY *CF			01-0770966-00 03020A	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
334006 LEFT	STROBE POWER SUPPLY	*CF		01-0790101-05 00319	MTH 21-Jan-2009		O/C			
334006 RIGHT	STROBE POWER SUPPLY	*CF		01-0790101-05 00321	MTH 21-Jan-2009		O/C			
335001 AFT	EMERGENCY LIGHTING UC020 BATTERY PACK	SBJD	A	9913-1 802	MTH 21-Dec-2012 HRS 690 LDG 421		O/C	0 0 0		
335001 FORWARD	EMERGENCY LIGHTING UC019 BATTERY PACK	*CF	A	9913-1 2258	MTH 21-Jan-2009		O/C			
340037	MAGNETOMETER MAG-3000A	*CF		501-1826-03 3162	MTH 21-Jan-2009		O/C			
341009	SAFE FLIGHT AOA UF004 SENSOR	*CF		C-12717-1 2356	MTH 21-Jan-2009		O/C			
341011	SAFE FLIGHT AOA UC009 COMPUTER	*CF		C13006-3 1413	MTH 21-Jan-2009		O/C			
341014	SAFE FLIGHT AOA FI003 INDEXER	*CF		C12763-1 1410	MTH 21-Jan-2009		O/C			
341016 SECONDARY	ADU	*CF		501-1890-08 3155	MTH 21-Jan-2009		O/C			
341017	MEGGITT SECONDARY FLIGHT (EI016) DISPLAY GH-3000	*CF	14	501-1741-2105 2061A	MTH 21-Jan-2009		O/C			
341105 <i>341103 : 1</i>	CONFIGURATION STRAPPING UNIT SWITCH CSU-3100	*CF		822-1363-002 31W6X	MTH 21-Jan-2009		O/C			
341105 <i>341103 : 2</i>	CONFIGURATION STRAPPING UNIT SWITCH CSU-3100	*CF		822-1363-002 31W7L	MTH 21-Jan-2009		O/C			
341106 <i>341104 : 1</i>	TAWS,WAAS OPTIONS CONTROL MODULE OCM-3100	*CF		822-1484-228 38NKT	MTH 21-Jan-2009		O/C			
341106 <i>341104 : 2</i>	TAWS,WAAS OPTIONS CONTROL MODULE OCM-3100	*CF		822-1484-228 38NKV	MTH 21-Jan-2009		O/C			
341107 NO. 1	(PILOT) AIR DATA COMPUTER ADC-3000	*CF	6	822-1109-126 357VK	MTH 21-Jan-2009		O/C			
341107 NO. 2	(COPILOT) AIR DATA COMPUTER ADC-3000	*CF	6	822-1109-126 33H7T	MTH 21-Jan-2009		O/C			
342005 NO. 1	COMPUTER-FLT GUIDANCE --	MCO	1	822-1108-143 34HOV	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
342005 NO. 2	COMPUTER-FLT GUIDANCE --	MCO	1	822-1108-143 33XVN	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
342008 NO. 1	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 351BC	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342008 NO. 2	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 31W3J	MTH 21-Jan-2009		O/C			
342009	IAPS ENVIRONMENTAL CONTROLLER IEC-3001	*CF	3	822-1167-001 31W8J	MTH 21-Jan-2009		O/C			
342020 AFT	INPUT/OUTPUT IOC CONCENTRATOR IOC-4110	MCO		822-2065-001 351DV	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
342020 FORWARD	INPUT/OUTPUT IOC CONCENTRATOR IOC-4110	MCO		822-2065-001 351DT	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
342033	MAINTENANCE DIAGNOSTIC COMPUTER MDC-3110	*CF	8	822-1987-007 350YT	MTH 21-Jan-2009		O/C			
342045 NO. 1	CONTROL DISPLAY PANEL DCP-3310	*CF		822-2388-001 36Y2L	MTH 21-Jan-2009		O/C			
342045 NO. 2	CONTROL DISPLAY PANEL	*CF		822-2388-001 3642N	MTH 21-Jan-2009		O/C			
342050 LEFT	FLUX DETECTOR FDU-3000	*CF		822-1193-001 41510	MTH 21-Jan-2009		O/C			
342050 RIGHT	FLUX DETECTOR FDU-3000	*CF		822-1193-001 41511	MTH 21-Jan-2009		O/C			
342054	ELEC HORIZ SIT IND (EHSI) -- EHSI-4000	*CF		501-1879-0102 1380A	MTH 22-Jan-2009		O/C			
342055	DATA CONCENTRATOR UNIT DCU-5010	CRD		822-1538-103 35GCM	MTH 02-Sep-2009 HRS 173.4 LDG 104		O/C	0 0 0		
342057 NO. 1	CURSOR CONTROL PANEL CCP-3310	*CF		822-2389-001 34M9V	MTH 21-Jan-2009		O/C			
342057 NO. 2	CURSOR CONTROL PANEL CCP-3310	*CF		822-2389-001 30GLR	MTH 22-Jan-2009		O/C			
342064 STANDBY 342064S	SECURAPLANE BATTERY	MCO		100-2410-04 0707080	MTH 07-May-2012 HRS 576 LDG 364		48	0	31-May-2016	5 m 27 d
342081 NO. 1 342082 : 1	PRIMARY FLIGHT (PFD) DISPLAY AFD-3310	MCO		822-1993-947 34X7B	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
342083 LEFT 342002 : 1	AHRS COMPUTER AHC-3000	*CF	3	822-1110-002 34PWY	MTH 21-Jan-2009		O/C			
342083 RIGHT 342002 : 2	AHRS COMPUTER AHC-3000	*CF	3	822-1110-002 34R5V	MTH 21-Jan-2009		O/C			
342084 NO. 1	MULTI FUNCTION (MFD) DISPLAY AFD-3320	MCO		822-2349-100 34X4W	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
342084 NO. 2	MULTI FUNCTION (MFD) DISPLAY AFD-3320	MCO		822-2349-100 34X7M	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
343001 NAVIGATION <i>343001A</i>	ANTENNA COUPLER	*CF		CI-120-5 263980	MTH 21-Jan-2009		O/C			
343001	GLIDESLOPE ANTENNA COUPLER	*CF		DGSC20-02 5066	MTH 21-Jan-2009		O/C			
343002 <i>343001 : B</i>	MARKER BEACON ANTENNA COUPLER	*CF		CI509 5066	MTH 21-Jan-2009		O/C			
344022	RADIO ALTIMETER ALT-55B TRANSCEIVER ALT-4000	*CF	12	822-0615-206 33NTB	MTH 21-Jan-2009		O/C			
344023 AFT	RADIO ALT RECEIVER ANTENNA	*CF		S67-2002 54344339	MTH 21-Jan-2009		O/C			
344023 FORWARD	RADIO ALT TRANSMITTER ANTENNA	*CF		S67-2002 54338042	MTH 21-Jan-2009		O/C			
344024	EGPWS COMPUTER S2800-903	*CF	11	965-0976-040-228-22 8 EMK528872	MTH 21-Jan-2009		O/C			
344030C	RCVR/TRANS/ANT,TURB-WEATHER -- RTA-852		KMCO 38	622-8439-004 4KF30	MTH 30-May-2014 HRS 911.5 LDG 555		O/C	7 0		
344103 <i>344102</i>	IAPS CARD CAGE	*CF		822-2191-001 3725P	MTH 21-Jan-2009		O/C			
345004 LEFT NO. 1	XPNDR BOTTOM ANTENNA	*CF		L10-611-14 1666	MTH 21-Jan-2009		O/C			
345004 RIGHT NO. 2	XPNDR BOTTOM ANTENNA	*CF		L10-611-14 1733	MTH 21-Jan-2009		O/C			
345005 LEFT NO. 1	TOP TRANSPONDER DIVERSITY ANTENNA	*CF		L10-611-14 1793	MTH 21-Jan-2009		O/C			
345005 RIGHT NO. 2	TOP TRANSPONDER DIVERSITY ANTENNA	*CF		L10-611-14 1779	MTH 21-Jan-2009		O/C			
345007 NO.1	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA	*CF		L10-611-14 1666	MTH 21-Jan-2009		O/C			
345007 NO.2	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA	*CF		L10-611-14 1733	MTH 21-Jan-2009		O/C			
345017	MARKER BEACON ANTENNA	*CF		MB10-754 0955	MTH 21-Jan-2009		O/C			
345018	GLIDESLOPE ANTENNA	*CF		RGS10-48 14197	MTH 21-Jan-2009		O/C			
345034 NO. 1	ATC TRANSPONDER TDR-94D	SBJD	29	622-9210-008 34JVB	MTH 21-Dec-2012 HRS 690 LDG 421		O/C	690 421		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345034 NO. 2	ATC TRANSPONDER TDR-94D	SBJD	29	622-9210-008 34JVN	MTH 21-Dec-2012 HRS 690 LDG 421		O/C	690 421		
345037 NO. 1	DME(TOP) TRANSCEIVER DME-4000	*CF	3	822-1466-001 358FV	MTH 21-Jan-2009		O/C			
345037 NO. 2	DME(BOTTOM) TRANSCEIVER DME-4000	*CF	3	822-1466-001 358PK	MTH 21-Jan-2009		O/C			
345048 NO. 1	FMS-CONTROL DISPLAY UNIT CDU-3000	*CF	7	822-0884-604 2YVLX	MTH 21-Jan-2009		O/C			
345048 NO. 2	FMS-CONTROL DISPLAY UNIT CDU-3000	*CF	7	822-0884-604 2YVLY	MTH 21-Jan-2009		O/C			
345057 NO. 1	NAV (VOR/ILS) RECEIVER NAV-4500	*CF	1	822-1579-001 35CHY	MTH 21-Jan-2009		O/C			
345057 NO. 2	NAV (VOR/ILS) RECEIVER NAV-4500	*CF	1	822-1579-001 35CJK	MTH 21-Jan-2009		O/C			
345065 NO. 1	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-998 34RHJ	MTH 21-Jan-2009		O/C			
345065 NO. 2	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 34RDN	MTH 21-Jan-2009		O/C			
345068	FILE SERVER UNIT FSU-5010	*CF	2	822-1543-101 33MKD	MTH 21-Jan-2009		O/C			
345069	XM WEATHER RECEIVER HUT -- XMWR-1000(S3100-437)	*CF		822-2031-002 352HB	MTH 21-Jan-2009		O/C			
345078 NO. 1 <i>345079C : 1</i>	GPS W/SBAS RECEIVER GPS-4000S	MCO	7	822-2189-002 3492C	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
345079 NO. 1 <i>345080 : L</i>	GPS FLT MGMT COMPUTER FMC-3000	MCO	23	822-0883-038 34GGF	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C	2 0		
345079 NO. 2 <i>345080 : R</i>	GPS FLT MGMT COMPUTER FMC-3000	MCO	23	822-0883-038 2RWMH	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
345079C NO. 2	GPS RECEIVER W/SBAS --	MCO	7	822-2189-002 3492G	MTH 03-Dec-2011 HRS 567.2 LDG 356		O/C			
345082	FLIGHT GUIDANCE PANEL			822-1107-116 36YDK	MTH 21-Jan-2009		O/C	0		
345083 <i>345080C</i>	FMS DATA BASE UNIT DBU-5000	*CF		822-2215-602 3551J	MTH 21-Jan-2009		O/C			
345093 NO.1	GPS ANTENNA	*CF		CI401-460 264231	MTH 21-Jan-2009		O/C			
345093 NO.2	GPS ANTENNA	*CF		S67-1575-132 4352463	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345201 LEFT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 264079	MTH 21-Jan-2009		O/C			
345201 RIGHT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 264078	MTH 21-Jan-2009		O/C			
346001	TCAS PROCESSOR TTR-4000	*CF	14	822-1294-002 162838	MTH 21-Jan-2009		O/C			
346002 BOTTOM	TCAS ANTENNA TRE-920	*CF		622-8973-001 39178	MTH 21-Jan-2009		O/C			
346002 TOP	TCAS ANTENNA TRE-920	*CF		622-8973-001 39104	MTH 21-Jan-2009		O/C			
351001	OXYGEN PRESSURE (EI002) GAGE MD-97	*CF		C668512-0101 E0811347	MTH 21-Jan-2009		O/C			
351002	GAUGE-OXYGEN PRESS -- MD-97	*CF		C668512-0101 E0811348	MTH 21-Jan-2009		O/C			
351004 COPILOT	OXYGEN MASK	MCO		MC10-16-150 124197	MTH 03-Dec-2011 HRS 567.2 LDG 356		72	0	31-Dec-2017	24 m 27 d
351004 PILOT	OXYGEN MASK	MCO		MC10-16-150 122642	MTH 03-Dec-2011 HRS 567.2 LDG 356		72	0	31-Dec-2017	24 m 27 d
351006	OXYGEN CYLINDER	MCO		804882-14 C07120615	MTH 04-May-2013 HRS 724.3 LDG 446		180		31-Oct-2022	82 m 27 d
Manufacture Date: 01-Oct-2007										
351007	OXYGEN REGULATOR	MCO		804881-01 C07100669	MTH 03-May-2013 HRS 724.3 LDG 446		O/C	67		
351008	PASSENGER OXYGEN CONTROL VALVE 9914067-19	*CF		P21006 3111	MTH 21-Jan-2009		O/C			
352001	PASSENGER OXYGEN ALTITUDE PRESSURE SWITCH	*CF		P24032 1414	MTH 21-Jan-2009		O/C			
361010	DOOR SOLENOID VALVE	*CF		5035-00-1 1552	MTH 21-Jan-2009		O/C			
361011 LEFT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 5BD107	MTH 21-Jan-2009		O/C			
361011 RIGHT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 9BD204	MTH 21-Jan-2009		O/C			
361101 LEFT	BLEED AIR OVERTEMP (ST017) SWITCH 9914149-2	*CF		1173T181-2 6827	MTH 21-Jan-2009		O/C			
361101 RIGHT	BLEED AIR OVERTEMP (ST014) SWITCH 9914149-2	*CF		1173T181-2 6820	MTH 21-Jan-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361102 LEFT	BLEED AIR MANIFOLD TEMPERATURE (TT001) SENSOR 9914519-2	*CF		1E51-1 11BC599	MTH 21-Jan-2009		O/C			
361102 RIGHT	BLEED AIR MANIFOLD TEMPERATURE (TT002) SENSOR 9914519-2	*CF		1E51-1 9BD548	MTH 21-Jan-2009		O/C			
361103 LEFT	HEAT B/A EXCHANGER 9912486-2	*CF		8230-2 S4883T1659	MTH 21-Jan-2009		O/C			
361103 RIGHT	HEAT B/A EXCHANGER 9912486-2	*CF		8230-2 S4883T1664	MTH 21-Jan-2009		O/C			
361104 LEFT	PRECOOLER VD003 VALVE 9914519-2	*CF		1406-7 0838	MTH 21-Jan-2009		O/C			
361104 RIGHT	PRECOOLER VD003 VALVE 9914519-2	*CF		1406-8 0898	MTH 21-Jan-2009		O/C			
361208 NO. 1	APU CHECK VALVE 9914171-1	*CF		8C210 7152	MTH 21-Jan-2009		O/C			
361208 NO. 2	APU CHECK VALVE 9914171-1	*CF		8C210 7168	MTH 21-Jan-2009		O/C			
361500 NO. 1	B/A CHECK VALVE 9914171-1	*CF		8C210 6633	MTH 21-Jan-2009		O/C			
361500 NO. 2	B/A CHECK VALVE 9914171-1	*CF		8C210 7200	MTH 21-Jan-2009		O/C			
361534	SERVICE AIR REGULATOR 9912510-1	*CF		1H75-18 7BD183	MTH 21-Jan-2009		O/C			
49APU1 490000	APU 9912484-1	*CF		3800722-1 P827	MTH 21-Jan-2009		E/C			
490001	APU ELECTRONIC CONTROL 9912484-1	*CF		2119552-3 86L0410	21-Jan-2009		O/C			
490003	BLEED AIR SHUTOFF VALVE 9912484-1	*CF		1413-7 0666	21-Jan-2009		O/C			
490004	DC AMMETER S3439-3	*CF		MD144-3 H0811746	21-Jan-2009		O/C			
490005	OVERHEAT DETECTOR 9912416-1	*CF		3001-212-1004/455-9 209494	21-Jan-2009		O/C			
490006	HOURMETER 9912416-1	*CF		C664503-0104 NSN	21-Jan-2009		O/C			
492003	COMPRESSOR ROTOR 9912416-1	*CF		3822523-003 080350114386	21-Jan-2009 APUS 0		12000	0	12000	11670
492004	TURBINE ROTOR 9912416-1	*CF		3842340-2 080134509697	21-Jan-2009 APUH 0 APUS 0		4000 4000	0 0	4000 4000	3668.7 3670

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
493000	FUEL CONTROL ASSEMBLY	*CF		3883900-1 0601486	21-Jan-2009		O/C			
493001	TEE-FLOW DIVIDER VALVE	*CF		66503-101165-001 08540	21-Jan-2009		O/C			
493002	FUEL SHUT-OFF VALVE			PN SN-UNKNOWN	21-Jan-2009		O/C	0		
494000	ELECTRICAL IGNITER LEAD	*CF		3888302-20 NSN	21-Jan-2009		O/C			
494001	IGNITER PLUG	*CF		304634-2 NSN	21-Jan-2009		O/C			
494002	IGNITION UNIT	*CF		3888000-7 080218090675	21-Jan-2009		O/C			
497006	RPM/MAX INDICATOR	*CF		MD680-4 H0810760	21-Jan-2009		O/C			
499000	LOW OIL PRESSURE SWITCH	*CF		3876351-1 080922701630	21-Jan-2009		O/C			
499001	LUBE PUMP ASSEMBLY	*CF		3881825-1 P1498	21-Jan-2009		O/C			
499002	OIL LEVEL SWITCH	*CF		3876318-3 080147000881	21-Jan-2009		O/C			
521003	ACOUSTIC LOWER FWD SEAL	*CF		9522-15 NSN	MTH 21-Jan-2009		O/C			
521004	ACOUSTIC UPPER SEAL	*CF		9522-11 NSN	MTH 21-Jan-2009		O/C			
521005	ACOUSTIC LOWER AFT SEAL	*CF		9522-13 NSN	MTH 21-Jan-2009		O/C			
527000	EMERGENCY EXIT SWITCH	*CF		8-405-04 B63300	MTH 21-Jan-2009		O/C			
531001	TRUNNION SUPPORT ASSEMBLY LEFT NOSE LANDING GEAR	*CF		6613020-55 NSN	MTH 21-Jan-2009 LDG 0		25500	0	25500	24873
531001	TRUNNION SUPPORT ASSEMBLY RIGHT NOSE LANDING GEAR	*CF		6613020-56 NSN	MTH 21-Jan-2009 LDG 0		25500	0	25500	24873
531002	ACTUATOR ATTACH FITTING NOSE GEAR	*CF		6611591-9 NSN	MTH 21-Jan-2009 LDG 0		25500	0	25500	24873
561001	MAIN WINDSHIELD LEFT	*CF		NP139731-1 08252H1276	MTH 21-Jan-2009		O/C			
561001	MAIN WINDSHIELD RIGHT	*CF		NP139731-2 08273H3895	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
561004 LEFT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-7	*CF		NP139722-7 08255H7059	MTH 21-Jan-2009		O/C			
561004 RIGHT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-8	*CF		NP139722-8 08213H5400	MTH 21-Jan-2009		O/C			
561005 LEFT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-33	*CF		NP139703-3 2723	MTH 21-Jan-2009		O/C			
561005 RIGHT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-34	*CF		NP139703-4 2622	MTH 21-Jan-2009		O/C			
562001 LEFT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 3537	MTH 21-Jan-2009		O/C			
562001 LEFT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 4357	MTH 21-Jan-2009		O/C			
562001 LEFT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 4316	MTH 21-Jan-2009		O/C			
562001 LEFT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 4318	MTH 21-Jan-2009		O/C			
562001 LEFT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 1503	MTH 21-Jan-2009		O/C			
562001 RIGHT NO. 1	EMERGENCY DOOR WINDOW 9914159-12	*CF		167400-03 4224	MTH 21-Jan-2009		O/C			
562001 RIGHT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 4290	MTH 21-Jan-2009		O/C			
562001 RIGHT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 4304	MTH 21-Jan-2009		O/C			
562001 RIGHT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 1617	MTH 21-Jan-2009		O/C			
562001 RIGHT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 4349	MTH 21-Jan-2009		O/C			
562001 RIGHT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 3961	MTH 21-Jan-2009		O/C			
571001 LEFT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-1 NSN	MTH 21-Jan-2009 LDG 0		23800	0	23800	23173
571001 RIGHT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-2 NSN	MTH 21-Jan-2009 LDG 0		23800	0	23800	23173
571002 LEFT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-1 NSN	MTH 21-Jan-2009 LDG 0		23800	0	23800	23173
571002 RIGHT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-2 NSN	MTH 21-Jan-2009 LDG 0		23800	0	23800	23173

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
571003 LEFT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-5 NSN	MTH 21-Jan-2009 LDG 0		23800	0	23800	23173
571003 RIGHT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-6 NSN	MTH 21-Jan-2009 LDG 0		23800	0	23800	23173
712001 LEFT	ENGINE AFT ISOLATOR 9912480-2 *CF			LM451-SA2 LK1271	MTH 21-Jan-2009 HRS 0		10000	0	10000	8885.6
712001 RIGHT	ENGINE AFT ISOLATOR 9912480-2 *CF			LM451-SA2 LK1532	MTH 21-Jan-2009 HRS 0		10000	0	10000	8885.6
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1 *CF			LM451-SA4 LK3279	MTH 21-Jan-2009 HRS 0		10000	0	10000	8885.6
712002 LEFT UPPER	FORWARD ENGINE ISOLATOR 9912480-1 *CF			LM451-SA4 LK3290	MTH 21-Jan-2009 HRS 0		10000	0	10000	8885.6
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1 *CF			LM451-SA4 LK2930	MTH 21-Jan-2009 HRS 0		10000	0	10000	8885.6
712002 RIGHT UPPER	FORWARD ENGINE ISOLATOR 9912480-1 *CF			LM451-SA4 3217	MTH 21-Jan-2009 HRS 0		10000	0	10000	8885.6
712005	ENG VIBRATION MONITOR 9912519-2 *CF			2789 070829	MTH 21-Jan-2009		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE			PW545C DF0017	MTH 21-Jan-2009		E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE			PW545C DF0018	MTH 21-Jan-2009		E/C			
721010 E1	ACCESSORY GEARBOX SHAFT *CF			30J2201-01 RWA34B161	MTH 21-Jan-2009		O/C			
721010 E2	ACCESSORY GEARBOX SHAFT *CF			30J2201-01 RWA34B158	MTH 21-Jan-2009		O/C			
722001 E1	OIL PUMP ASSEMBLY *CF			30J3365-01 EC01A001A906	MTH 21-Jan-2009		O/C			
722001 E2	OIL PUMP ASSEMBLY *CF			30J3365-01 EC01A001A907	MTH 21-Jan-2009		O/C			
723000 E1	LP COMPRESSOR SHAFT *CF			30J3206-01 DDAA007A888	MTH 21-Jan-2009 LDG 5		20000	0	20005	19378
723000 E2	LP COMPRESSOR SHAFT *CF			30J3206-01 DDAA007A887	MTH 21-Jan-2009 LDG 5		20000	0	20005	19378
723010 E1	LP COMPRESSOR FAN ROTOR *CF			30J2681-01 A002DC4H	MTH 21-Jan-2009 LDG 5		10000	0	10005	9378
723010 E2	LP COMPRESSOR FAN ROTOR *CF			30J2681-01 A002D6N2	MTH 21-Jan-2009 LDG 5		10000	0	10005	9378

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
723020 E1	LP COMPRESSOR BOOST ROTOR *CF			30J2210-01 TXA1B6810	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
723020 E2	LP COMPRESSOR BOOST ROTOR *CF			30J2210-01 TXA1B6742	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
723030 E1	1ST STAGE HP COMPRESSOR ROTOR *CF			30J2821-01 A002D47W	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
723030 E2	1ST STAGE HP COMPRESSOR ROTOR *CF			30J2821-01 A002D479	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
723040 E1	2ND STAGE HP COMPRESSOR ROTOR *CF			30J2429-01 A002D6D2	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
723040 E2	2ND STAGE HP COMPRESSOR ROTOR *CF			30J2429-01 A002D6D4	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
723060 E1	CENTRIFUGAL IMPELLER *CF			30J1450-01 A002D74C	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
723060 E2	CENTRIFUGAL IMPELLER *CF			30J1450-01 A002DA53	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
724001 E1 INNER	COMBUSTION CHAMBER LINER *CF			30J2342-01 A002DCX6	MTH 21-Jan-2009		O/C			
724001 E1 OUTER	COMBUSTION CHAMBER LINER *CF			30J2590-01 A002CW6K	MTH 21-Jan-2009		O/C			
724001 E2 INNER	COMBUSTION CHAMBER LINER *CF			30J2342-01 A002DCX7	MTH 21-Jan-2009		O/C			
724001 E2 OUTER	COMBUSTION CHAMBER LINER *CF			30J2590-01 A002CW6N	MTH 21-Jan-2009		O/C			
725010 E1	1ST-STAGE TURBINE DISK *CF			30J1551-01 A002D51Y	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
725010 E2	1ST-STAGE TURBINE DISK *CF			30J1551-01 A002CL9P	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
725020 E1	2ND-STAGE TURBINE DISK *CF			30H3172 ABT00541	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
725020 E2	2ND-STAGE TURBINE DISK *CF			30H3172 ABT00669	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
725030 E1	3RD-STAGE TURBINE DISK *CF			30H3173 ABT00446	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
725030 E2	3RD-STAGE TURBINE DISK *CF			30H3173 ABT00737	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
725040 E1	4TH-STAGE TURBINE DISK *CF			30H3174 ABT00284	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
725040 E2	4TH-STAGE TURBINE DISK 9914413-1	*CF		30H3154 MAA45275	MTH 21-Jan-2009 LDG 5		13500	0	13505	12878
733001 LEFT	FUEL FLOW TRANSMITTER 9914413-1	*CF		9-231-28 L9993	MTH 21-Jan-2009		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9914413-1	*CF		9-231-28 L9986	MTH 21-Jan-2009		O/C			
733004 LEFT	FUEL PRESSURE SWITCH 9914112-3	*CF		6057-3 2825	MTH 21-Jan-2009		O/C			
733004 RIGHT	FUEL PRESSURE SWITCH 9914112-3	*CF		6057-3 2822	MTH 21-Jan-2009		O/C			
732001 E1	HYDROMECHANICAL FUEL CONTROL 30J3050-03	*CF		1007800-4 F69123	MTH 21-Jan-2009		O/C			
732001 E2	HYDROMECHANICAL FUEL CONTROL 30J3050-02	ICT		1007800-3 F65605	MTH 10-Dec-2009 HRS 261		O/C	0		
732002 E2	ELECTRICAL WIRING HARNESS SBJD			30J2970-06 ADXAX000907	MTH 11-Jun-2015 HRS 1097.7 LDG 614		O/C	0 0 0		
741001 E1	IGNITION EXCITER 31J2807-07	*CF		500335-1 NNA08134453	MTH 21-Jan-2009		O/C			
741001 E2	IGNITION EXCITER 31J2807-07	*CF		500335-1 NNA08154824	MTH 21-Jan-2009		O/C			
742001 E1 INBOARD	IGNITOR 30J2825-01	*CF		502600-1 NSN	MTH 21-Jan-2009		O/C			
742001 E1 OUTBOARD	IGNITOR 30J2825-01	*CF		502600-1 NSN	MTH 21-Jan-2009		O/C			
742001 E2 INBOARD	IGNITOR 30J2825-01	*CF		502600-1 NSN	MTH 21-Jan-2009		O/C			
742001 E2 OUTBOARD	IGNITOR 30J2825-01	*CF		502600-1 NSN	MTH 21-Jan-2009		O/C			
742002 E1	SHORT IGNITOR LEAD 30J3125-01	*CF		508122-1 NNA08218986	MTH 21-Jan-2009		O/C			
742002 E2	SHORT IGNITOR LEAD 30J3125-01	*CF		508122-1 NNA08084406	MTH 21-Jan-2009		O/C			
742003 E1	LONG IGNITOR LEAD 30J3125-02	*CF		508122-2 NNA08146363	MTH 21-Jan-2009		O/C			
742003 E2	LONG IGNITOR LEAD 30J3125-02	*CF		508122-2 NNA08156815	MTH 21-Jan-2009		O/C			
751003 E1	COMPRESSOR BLEED VALVE ASSY *CF			30J2954-01 AHX012064	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
751003 E2	COMPRESSOR BLEED VALVE ASSY	*CF		30J2954-01 AHX012024	MTH 21-Jan-2009		O/C			
751004 E1	BLEED SERVO VALVE	KICT		30J3491-01 TR6388	MTH 28-Jan-2014 HRS 856 LDG 523		O/C	0		
751004 E2	BLEED SERVO VALVE	KICT		30J3491-01 TR6390	MTH 28-Jan-2014 HRS 856 LDG 523		O/C	0		
751005 E1	LINEAR TRANSDUCER	*CF		30J3053-01 1035	MTH 21-Jan-2009		O/C			
751005 E2	LINEAR TRANSDUCER	*CF		30J3053-01 1031	MTH 21-Jan-2009		O/C			
761001 E1	ELECTRONIC ENGINE CONTROL	MCO		1012400-3-005 2009017279	MTH 03-May-2013 HRS 724.3 LDG 446		O/C			
761001 E2	ELECTRONIC ENGINE CONTROL	MCO		1012400-3-005 2012010016	MTH 03-May-2013 HRS 724.3 LDG 446		O/C			
774001 E1	DATA COLLECTION UNIT	MCO		30J3470-01 13-706	MTH 03-May-2013 HRS 724.3 LDG 446		O/C	0		
774001 E2	DATA COLLECTION UNIT	ICT		54204-01 3AD18DP09-1179	MTH 10-Dec-2009 HRS 261		O/C	0		
783001 LEFT ENGINE <i>783001X : E1**L</i>	THRUST REVERSER ASSEMBLY	*CF		64ND-78002-5 1437	MTH 21-Jan-2009		O/C			
783001 RIGHT ENGINE <i>783001X : E2**R</i>	THRUST REVERSER ASSEMBLY	*CF		64ND-78002-6 1438	MTH 21-Jan-2009		O/C			
783002 LEFT	THRUST REVERSER VALVE	*CF		4221 0748	MTH 21-Jan-2009		O/C			
783002 RIGHT	THRUST REVERSER VALVE	*CF		4221 0743	MTH 21-Jan-2009		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 3135	MTH 21-Jan-2009		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 3133	MTH 21-Jan-2009		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 3134	MTH 21-Jan-2009		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 3140	MTH 21-Jan-2009		O/C			
783100 LEFT	THRUST REVERSER MANIFOLD ASSEMBLY	*CF		8245 0747	MTH 21-Jan-2009		O/C			
783100 RIGHT	THRUST REVERSER MANIFOLD ASSEMBLY	*CF		8245 0735	MTH 21-Jan-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783101 LEFT	ARM PRESSURE SWITCH	*CF		80637-1 1218	MTH 21-Jan-2009		O/C			
783101 RIGHT	ARM PRESSURE SWITCH	*CF		80637-1 1191	MTH 21-Jan-2009		O/C			
783102 LEFT	THRUST REVERSER ISOLATION VALVE	*CF		4222 0755M	MTH 21-Jan-2009		O/C			
783102 RIGHT	THRUST REVERSER ISOLATION VALVE	*CF		4222 0731M	MTH 21-Jan-2009		O/C			
783103 LEFT INBOARD	STOW LIMIT SWITCH	*CF		53ND78304-1 NSN	MTH 21-Jan-2009		O/C			
783103 LEFT OUTBOARD	STOW LIMIT SWITCH	*CF		53ND78304-1 NSN	MTH 21-Jan-2009		O/C			
783103 RIGHT INBOARD	STOW LIMIT SWITCH	*CF		53ND78304-1 NSN	MTH 21-Jan-2009		O/C			
783103 RIGHT OUTBOARD	STOW LIMIT SWITCH	*CF		53ND78304-1 NSN	MTH 21-Jan-2009		O/C			
783104 LEFT	DEPLOY LIMIT SWITCH	*CF		53ND78304-5 NSN	MTH 21-Jan-2009		O/C			
783104 RIGHT	DEPLOY LIMIT SWITCH	*CF		53ND78304-5 NSN	MTH 21-Jan-2009		O/C			
793002 LEFT	OIL TEMP XMTR SENSOR	*CF		102-00083 07129	MTH 21-Jan-2009		O/C			
793002 RIGHT	OIL TEMP XMTR SENSOR	*CF		102-00083 06924	MTH 21-Jan-2009		O/C			
793102 LEFT	ENGINE OIL TRANSMITTER	*CF		APTE-237D-1000-25 0D 751212480	MTH 21-Jan-2009		O/C			
793102 RIGHT	ENGINE OIL TRANSMITTER	*CF		APTE-237D-1000-25 0D 751212491	MTH 21-Jan-2009		O/C			
793117 LEFT	OIL PRESSURE SWITCH	*CF		1153P0098-01 2151	MTH 21-Jan-2009		O/C			
793117 RIGHT	OIL PRESSURE SWITCH	*CF		1153P0098-01 2222	MTH 21-Jan-2009		O/C			
793003 E1	FUEL OIL HEAT EXCHANGER	*CF		31J2955-02 04244321	MTH 21-Jan-2009		O/C			
793003 E2	FUEL OIL HEAT EXCHANGER	*CF		31J2955-02 04302593	MTH 21-Jan-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
793020 E1 LEFT	OIL LEVEL INDICATOR			PN SN-UNKNOWN	MTH 21-Jan-2009		O/C	0		
793020 E1 RIGHT	OIL LEVEL INDICATOR			PN SN-UNKNOWN	MTH 21-Jan-2009		O/C	0		
793020 E2 LEFT	OIL LEVEL INDICATOR			PN SN-UNKNOWN	MTH 21-Jan-2009		O/C	0		
793020 E2 RIGHT	OIL LEVEL INDICATOR			PN SN-UNKNOWN	MTH 21-Jan-2009		O/C	0		
801000 LEFT ENGINE	STARTER/GENERATOR 9912499-6	KMCO		300SGL138Q-4 4037XL	MTH 30-May-2014 HRS 911.5 LDG 555		1000	0	1911.5	797.1
801000 RIGHT ENGINE	STARTER/GENERATOR 9912499-6	KMCO		300SGL138Q-4 3525XL	MTH 30-May-2014 HRS 911.5 LDG 555		1000	0	1911.5	797.1
801100 APU	STARTER/GENERATOR 9912499-31	*CF		300SGL138Q-6 8394XL	MTH 21-Jan-2009 APUH 0		1000	0	1000	668.7



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) INFORMATIONAL						-			
	MOC :									
SL 560XL-03-01 R1	SUPPLEMENTAL TYPE CERTIFICATE (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013) INFORMATIONAL						-			
	MOC :									
SL 560XL-99-01 R4	CESCOM PRICES INFORMATIONAL						-			
	MOC :									
SL 560XL-99-03 R1	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE INFORMATIONAL						-			
	MOC :									
SL 560XL-99-04	CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS INFORMATIONAL						A/R			
	MOC :									
SL 560XL-99-05	CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION INFORMATIONAL						A/R			
	MOC :									
SL CIL-99-01 R1	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL						-			
	MOC :									
SL CIL-99-01 R2	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL						-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL						-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS RECOMMENDED MTH						-			
	MOC :									
SL CIL-20-01 R2	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL						-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL						-			
	MOC :									
SL CIL-99-03 R1	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) RECOMMENDED						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VVY**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED	MTH		-			
MOC :										
SL 560XL-20-01 R10	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
MOC :										
SL CIL-21-03	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SB 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION			INFORMATIONAL			-			
MOC :										
SB 560XL-24-02 R1 24SB-02 : XLR1	CONCORDE BATTERY INSTALLATION		*CF	OPTIONAL	MTH		-			
MOC :										
SB 560XL-24-16	APU STARTER/GENERATOR WIRING IMPROVEMENT		MCO	RECOMMENDED	MTH 07-May-2012 HRS 576 LDG 364		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-24-17	TAILCONE INVERTER RELOCATION		MCO	DISCRETIONARY	MTH 07-May-2012 HRS 576 LDG 364		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-24-18	ELECTRICAL POWER - STANDBY POWER WIRING MODIFICATION		MCO	RECOMMENDED	MTH 07-May-2012 HRS 576 LDG 364		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-25-11 R1 25SB-11 : XLR1	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)		*CF	OPTIONAL	MTH		-			
MOC :										
SB 560XL-25-12 R1 25SB-12 : XLR1	GLARESHIELD LEATHER STRIP INSTALLATION		*CF	OPTIONAL	MTH		-			
MOC :										
SB 560XL-25-18	EQUIPMENT / FURNISHINGS - PASSENGER SEAT WEB GUIDE IMPROVEMENT			OPTIONAL			-			
MOC :										
SL 560XL-25-13	TRANSMITTAL OF ROCKWELL COLLINS AIRSHOW 4000 SERVICEBULLETIN 30, CORRECTION OF HARD DRIVE MOUNTING SCREWS - MOD U		MCO	RECOMMENDED	MTH 08-Dec-2010 HRS 507.7 LDG 318		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY VISUAL INSPECTION. SERVICE LETTER DOES NOT APPLY DUE TO AIRCRAFT IS NOT EQUIPPED WITH AIRSHOW 4000 SYSTEM. NO FURTHER ACTION REQUIRED. PLEASE UPDATE CESCOM.										
SL 560XL-25-14	PASSENGER SEAT INSPECTION		MCO	MANDATORY	MTH 09-Dec-2010 HRS 507.7 LDG 318		A/R			N/A
MOC : NOT APPLICABLE - SERVICE LETTER, SL560XL-25-14, DOES NOT APPLY TO THIS AIRCRAFT DUE TO AIRCRAFT SERIAL NUMBER.										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-25-15 R1	TRANSMITTAL OF AIRCRAFT BELTS INC. SB-BUC062-A001 INSPECTION OF BUCKLES FOR PROPER OPERATION	MCO		MANDATORY	MTH 08-Dec-2010 HRS 507.7 LDG 318		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH BY ACTIVATING ALL PASSENGER SEAT BELT LOCKS WITH SUPPLIED TOOL PART NO: PA64051 AND VISUALLY INSPECTING FOR GAP PER SERVICE LETTER INSTRUCTIONS. NO DEFECTIVE BUCKLES FOUND AT THIS TIME.									
SL 560XL-25-15	TRANSMITTAL OF AIRCRAFT BELTS INC. SB-BUC062-A001 INSPECTION OF BUCKLES FOR PROPER OPERATION			MANDATORY	MTH		A/R			
	MOC :									
SL 560XL-25-16	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF IPECO SERVICE BULLETINS 428-25-01, AND 429-25-01, ADDITION OF CABLE CLIP	MCO		RECOMMENDED	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			N/A
	MOC : NOT APPLICABLE - SL560XL-25-16 & IPECO SB428-25-01/SB429-25-01 DUE TO SEAT PNS AND SNS ARE NOT WITHIN SB REQUIREMENTS. PLEASE REMOVE FROM CESCOM									
SL 560XL-25-17	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR	MCO		RECOMMENDED	MTH 03-May-2013 HRS 724.3 LDG 446		-			Complete
	MOC : COMPLIED WITH									
SB 560XL-26-03 26SB-03 : XL	FIRE PROTECTION - ENGINE FIRE BOTTLE ARM ANNUNCIATION MODIFICATION	ICT		MANDATORY	MTH 10-Dec-2009 HRS 261		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-27-32 R1	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION			RECOMMENDED			A/R			
	MOC :									
SB 560XL-27-32 R2	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION	MCO		RECOMMENDED	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-27-32	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION			RECOMMENDED			A/R			
	MOC : - SUPERSEDED BY REVISION 1									
SB 560XL-27-35 R1	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
	MOC :									
SB 560XL-27-35	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
	MOC :									
SL 560XL-27-14 27SL-14 : XL	HORIZONTAL AND VERTICAL STABILIZER EROSION BOOT INSTALLATION	*CF		OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-27-18	ELEVATOR TRIM CABLE REPLACEMENT INTERVALS INFORMATIONAL						-			
MOC :										
SL 560XL-27-20 R1	RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION MANDATORY			MTH			-			
MOC :										
SL 560XL-27-20 R2	RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION KICT MANDATORY			MTH 28-Jan-2014 HRS 856 LDG 523			-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL560XL-27-20 R2; RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION, DATED JANUARY 18, 2014.										
SL 560XL-27-20	RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION MANDATORY			MTH			-			
MOC :										
SL 560XL-27-21	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY INSPECTION KICT MANDATORY			MTH 28-Jan-2014 HRS 856 LDG 523			-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL560XL-27-21; RUDDER TORQUE TUBE/SECTOR ASSEMBLY INSPECTION, DATED JANUARY 18, 2014.										
SL 560XL-27-33	ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD ICT MANDATORY			MTH 22-Jan-2015 HRS 997.3 LDG 604			-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL560XL-27-33 ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD, DATED NOVEMBER 5, 2014.										
SL 560XL-27-34 R1	RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION MANDATORY			MTH HRS			DUE DUE DUE		31-Dec-2016 1890	12 m 27 d 775.6
MOC :										
SL 560XL-27-34	RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION MANDATORY			MTH			-			
MOC :										
SL 560XL-27-35	FLIGHT CONTROLS - AFT AILERON SECTOR ASSEMBLY INSPECTION MANDATORY			DAYS			180		14-May-2016	New Req
MOC :										
SL 560XL-28-03	FUEL - MOTIVE FLOW SHUTOFF VALVE O-RING REPLACEMENT MCO RECOMMENDED			MTH 07-May-2012 HRS 576 LDG 364			A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-29-03 29SL-03 : XL	ENGINE HYDRAULIC HOSE INSPECTION ICT RECOMMENDED			MTH 10-Dec-2009 HRS 261			A/R			N/A
MOC : NOT APPLICABLE										
SL 560XL-29-04	HYDRAULIC MANIFOLD CONTROL VALVE WIRE BUNDLE INSPECTION RECOMMENDED			MTH HRS			300		1297.3	182.9
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-30-01 R1	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES INFORMATIONAL						-			
MOC :										
SB 560XL-31-05 31SB-05 : XL	DATA CONCENTRATOR UNIT SOFTWARE UPGRADE CRD			MANDATORY	DAYS 02-Sep-2009 HRS 173.4 LDG 104		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-31-05	TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001 MCO			MANDATORY	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-32-38 R1	LANDING GEAR - REMOVE THE QUICK DISCONNECT FROM THE NOSE LANDING GEAR TORQUE LINK OPTIONAL						A/R			
MOC :										
SB 560XL-32-38 32SB-38 : XL	REMOVE THE QUICK DISCONNECT FROM THE NOSE LANDING GEAR TORQUE LINK *CF			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-32-41 R1	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-7 MCO			MANDATORY	MTH 07-May-2012 HRS 576 LDG 364		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-32-42 R1	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT OPTIONAL						-			
MOC :										
SB 560XL-32-42 R2	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT OPTIONAL						-			
MOC :										
SB 560XL-32-42	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT OPTIONAL						-			
MOC :										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL INFORMATIONAL						-			
MOC :										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL						-			
MOC :										
SL 560XL-32-22 32SL-22 : XL	LANDING GEAR COMPONENT PLACARD INSTALLATION MCO			OPTIONAL	MTH 07-May-2012 HRS 576 LDG 364		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-32-23 32SL-23 : XL	EMERGENCY GEAR RELEASE INSPECTION ICT			RECOMMENDED	MTH 10-Dec-2009 HRS 261		A/R			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-32-24 R1	TRANSMITTAL OF CURTISS WRIGHT SB 049801-32-01, LANDING GEAR CONTROL ALTERNATE LED LIGHTING BULB									
	CANCELLED									
	MOC :									
SL 560XL-32-26	REPLACEMENT OF THE COTTER PIN FOR THE EMERGENCY GEAR-RELEASE	MCO		MANDATORY	MTH 08-Dec-2010 HRS 507.7 LDG 318		A/R			N/A
	MOC : NOT APPLICABLE - THIS SERVICE LETTER DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER EFFECTIVITY. PLEASE UPDATE CESCOM.									
SL 560XL-32-27 R1	HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION			MANDATORY	DAYS HRS		90 300		01-Oct-2014 1215.33	-14 m 3 d 100.93
	MOC :									Over Due
SL 560XL-32-27	HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION	ICT		MANDATORY	MTH 22-Jan-2015 HRS 997.3 LDG 604		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SL560XL-32-27 HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION, DATED JULY 3, 2014.									
SL 560XL-33-10	AFT SIDELEDGE DIVIDER LIGHT INSPECTION/REPLACEMENT	MCO		RECOMMENDED	MTH 08-Dec-2010 HRS 507.7 LDG 318		A/R			N/A
	MOC : NOT APPLICABLE - THIS SL IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED IN AIRCRAFT. THIS AIRCRAFT HAS LED INTERIOR LIGHTING UNAFFECTED BY THIS SL. PLEASE UPDATE CESCOM.									
SB 560XL-34-37 34SB-37 : XL	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) STEEP APPROACH SWITCH INSTALLATION	*CF		OPTIONAL	MTH		-			
	MOC :									
SB 560XL-34-40 R1 34SB-40 : XLR1	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) UPGRADE	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-34-41 R2 34SB-41 : XLR2	HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-34-43 R1 34SB-43 : XLR1	UNIVERSAL AVIONICS PERFORMANCE DATABASE UPGRADE	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-34-45 R1 34SB-45 : XLR1	ENHANCED VISION SYSTEMS (EVS) INSTALLATION	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-34-49 R1 34SB-49 : XLR1	RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-34-50 R2 34SB-50 : XLR2	IC-615 VERTICAL GLIDE PATH AND FLIGHT DIRECTOR IMPROVEMENTS	ICT		RECOMMENDED	MTH 10-Dec-2009 HRS 261		A/R			N/A
	MOC : NOT APPLICABLE									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-34-63 R1	XLS+ FMS 4.0 (WAAS) UPGRADE AND V-SPEEDS DATABASE INSTALLATION	MCO		RECOMMENDED	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-34-63 34SB-63 : XL	XLS+ FMS 4.0 (WAAS) UPGRADE AND V-SPEEDS DATABASE INSTALLATION			RECOMMENDED			A/R			
	MOC :									
SB 560XL-34-64 34SB-64 : XL	CAT II LANDING OPERATION OPTION			OPTIONAL	MTH		A/R			
	MOC :									
SB 560XL-34-65 34SB-65 : XL	XLS+ ADAPTIVE FLIGHT DISPLAYS (AFD) SOFTWARE AND HARDWARE UPDATE	MCO		RECOMMENDED	MTH 03-Dec-2011 HRS 567.2 LDG 356		300			Complete
	MOC : COMPLIED WITH									
SB 560XL-34-68 R1	NAVIGATION - AFD AOA CONFIGURATION WIRING INSTALLATION	MCO		RECOMMENDED	MTH 07-May-2012 HRS 576 LDG 364		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-34-68	AFD AOA CONFIGURATION WIRING INSTALLATION	MCO		RECOMMENDED	MTH 08-Dec-2010 HRS 507.7 LDG 318		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH BY MODIFICATION OF WIRING PER SERVICE BULLETIN INSTRUCTIONS. OPERATIONAL CHECKS GOOD.									
SB 560XL-34-73	TRAFFIC SURVEILLANCE SYSTEM (TTR-4000) TCAS II SOFTWARE 7.1 UPGRADE			OPTIONAL			-			
	MOC :									
SB 560XL-34-74	GPS-4000S SOFTWARE UPDATE			RECOMMENDED	MTH		-			
	MOC :									
ASL 560XL-34-08 34ASL08 : XL	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	ICT		MANDATORY	MTH 21-Jan-2009 HRS 7		-			N/A
	MOC : NOT APPLICABLE									
SL CIL-34-04	TDR-94/94D TRANSPONDER ALL-CALL			INFORMATIONAL			-			
	MOC :									
SL CIL-35-02	OXYGEN - TRANSMITTAL OF ZODIAC AEROTECHNICS SERVICE BULLETIN MC10-35-274			MANDATORY	MTH HRS		6 200		12-Dec-2015 1250.73	8 d 136.33
	MOC :									
SL 560XL-35-03 35SL-03 : XL	TRANSMITTAL OF AVOX SYSTEMS SERVICE BULLETIN 36758-35-01	ICT		RECOMMENDED	MTH 10-Dec-2009 HRS 261		A/R			N/A
	MOC : NOT APPLICABLE									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-35-04 R1	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	MCO		MANDATORY	MTH 07-May-2012 HRS 576 LDG 364		-			Complete
	MOC : COMPLIED WITH									
SL 560XL-35-04 R2	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
	MOC :									
SB 560XL-38-03	TOILET OVERRIDE RELAY INSTALLATION			OPTIONAL			-			
	MOC :									
SL 560XL-38-01	TRANSMITTAL OF MONOGRAM SYSTEMS SERVICE INFORMATION LETTER SIL15900-023	MCO		RECOMMENDED	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-49-17	AUXILIARY POWER - AUXILIARY POWER UNIT MOUNT BOLT CHANGE			OPTIONAL			-			
	MOC :									
SB 3615880-49-8149 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			New Req
	MOC :									
SB 3822101-49-8148 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			New Req
	MOC :									
SB 3881800-49-7523 R4	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PN 3876255-2 WITH PN 3876351-1 AND REIDENTIFY LUBE PUMP FROM PN 3881800-1 TO PN 3881825-1, ON RE100[XL] AND RE100[LJ] APUS			RECOMMENDED			-			
	MOC :									
SB 49-7933 R4	OIL - GENERAL - APPROVED OILS						-			
	MOC :									
SB 49-7933 R5	OIL - GENERAL - APPROVED OILS						-			
	MOC :									
SB 49-7992 R1	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
	MOC :									
SB 49-7992	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 49-7997 R2	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									
	MOC :									
SB 49-7997 R3	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									
	MOC :									
SB 49-7997 R4	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									
	MOC :									
SB 70721598-49-8168 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS									
				RECOMMENDED						New Req
	MOC :									
SB 70721725-49-8152 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS									
				RECOMMENDED						New Req
	MOC :									
SB RE100-49-7896 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL FILLER NECK AND (DIPSTICK) CAP, PN 361-530-9354, WITH OIL FILLER NECK CAP, PN 361-530-9355, ON THE RE100 APU OPTIONAL									
	MOC :									
SB RE100-49-7933 R3	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS									
				RECOMMENDED						
	MOC :									
SB RE100-49-8139	INCREASE THE INSTALLATION TORQUE AND ADD THE USE OF LOCKING COMPOUND DURING CARBON SEAL ASSEMBLY ON THE RE100 APU									
				RECOMMENDED						
	MOC :									
SL 560XL-52-07	DOORS - EXTERIOR DOOR SWITCH IMPROVEMENT INFORMATIONAL							A/R		
	MOC :									
SB 560XL-53-13 R1	FUSELAGE - NOSE DRIP CAP BOND INSPECTION MCO MANDATORY				MTH 03-May-2013 HRS 724.3 LDG 446			A/R		Complete
	MOC : COMPLIED WITH									
SB 560XL-53-13	FUSELAGE - NOSE DRIP CAP BOND INSPECTION MCO MANDATORY				MTH 03-May-2013 HRS 724.3 LDG 446			A/R		Complete
	MOC : COMPLIED WITH									
SB 560XL-53-14	FUSELAGE - CARBON FIBER STRAKE MODIFICATION OPTIONAL									
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-53-15	FUSELAGE - FASTENER INSTALLATION F.S. MCO			115.20 MANDATORY	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-53-16	FUSELAGE - STINGER DRAIN INSTALLATION MCO			MANDATORY	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			Complete
MOC : COMPLIED WITH										
ASL 560XL-53-08 R1	AFT CANTED BULKHEAD DRAIN INSTALLATION UNK			MANDATORY	DAYS 12-Apr-2011 HRS 535.7 LDG 336		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED ASL560XL-53-08 REVISION 1 ON 4-12-11 WORK ORDER 11-0107/2.										
ASL 560XL-53-08	AFT CANTED BULKHEAD DRAIN INSTALLATION MANDATORY				DAYS		A/R			
MOC : - SUPERSEDED BY REVISION 1										
SL 560XL-53-07 53SL-07 : XL	LOWER SKIN ASSEMBLY FASTENER INSPECTION ICT			MANDATORY	MTH 10-Dec-2009 HRS 261		-			N/A
MOC : NOT APPLICABLE										
SL 560XL-53-17	FUSELAGE - DORSAL DUCT INSPECTION MCO			RECOMMENDED	MTH 03-May-2013 HRS 724.3 LDG 446		-			Complete
MOC : COMPLIED WITH										
SL 560XL-55-01 R2	PIVOT FITTING INSPECTION			MANDATORY	MTH HRS		6000		6000	4885.6
MOC :										
SL 560XL-56-03	OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION MCO			MANDATORY	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-71-11 R1	ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION OPTIONAL						-			
MOC :										
SB 560XL-71-11	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION OPTIONAL						A/R			
MOC :										
SB 560XL-71-12	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE REMOVAL OPTIONAL						-			
MOC :										
SL CIL-71-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30463 OPTIONAL						-			
MOC :										
ASL 560XL-72-19 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF MANDATORY						A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASL 560XL-72-19 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF			MANDATORY			A/R			
MOC :										
SL 560XL-72-15 72SL-15 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30383, INSPECTION OF TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE SERVO VALVE	ICT		RECOMMENDED	MTH 10-Dec-2009 HRS 261		A/R			N/A
MOC : NOT APPLICABLE										
SL 560XL-72-16 72SL-16 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30368, TURBOFAN ENGINE INTERCOMPRESSOR BLEEDVALVE SERVO VALVE - INSPECTION	ICT		RECOMMENDED	MTH 10-Dec-2009 HRS 261		A/R			N/A
MOC : NOT APPLICABLE										
SL 560XL-72-17 LEFT ENGINE	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	MCO		MANDATORY	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			N/A
MOC : NOT APPLICABLE - THIS SERVICE LETTER AND P&WC SB 30409 ARE NOT APPLICABLE TO THIS AIRCRAFT SERIAL NO OR THIS ENGINE MODEL (545C)										
SL 560XL-72-17 RIGHT ENGINE	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	MCO		MANDATORY	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			N/A
MOC : NOT APPLICABLE - THIS SERVICE LETTER AND P&WC SB 30409 ARE NOT APPLICABLE TO THIS AIRCRAFT SERIAL NO OR THIS ENGINE MODEL (545C)										
SB PW300-72-30446 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW300-72-30446 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30369 R1	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30369 R1	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30371 R1	TURBOFAN ENGINE - ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE - INTRODUCTION			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30371 R1	TURBOFAN ENGINE - ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE - INTRODUCTION									
				CATEGORY 6						

E2

MOC :

SB PW500-72-30371 R2	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE									
				CATEGORY 10						

E1

MOC :

SB PW500-72-30371 R2	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE									
				CATEGORY 10						

E2

MOC :

SB PW500-72-30376 R1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR									
				CATEGORY 7			A/R			

E1

MOC :

SB PW500-72-30376 R1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR									
				CATEGORY 7			A/R			

E2

MOC :

SB PW500-72-30379 R1	REPLACEMENT/MODIFICATION OF BY-PASS DUCTS									
				CATEGORY 7						

E1

MOC :

SB PW500-72-30379 R1	REPLACEMENT/MODIFICATION OF BY-PASS DUCTS									
				CATEGORY 7						

E2

MOC :

SB PW500-72-30379 E1	REPLACEMENT/MODIFICATION BY-PASS DUCTS									
				CATEGORY 7			A/R			

MOC :

SB PW500-72-30379 E2	REPLACEMENT/MODIFICATION BY-PASS DUCTS									
				CATEGORY 7			A/R			

MOC :

SB PW500-72-30384 R1	REPLACEMENT OF AIR/OIL SEPARATOR									
				CATEGORY 6			A/R			

E1

MOC :

SB PW500-72-30384 R1	REPLACEMENT OF AIR/OIL SEPARATOR									
				CATEGORY 6			A/R			

E2

MOC :



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30393 R1 E1	REPLACEMENT OF EEC SUPPORT BRACKETS			RECOMMENDED			-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30393 R1 E2	REPLACEMENT OF EEC SUPPORT BRACKETS			RECOMMENDED			-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30393 E1	REPLACEMENT OF EEC SUPPORT BRACKETS	CR9		CATEGORY 3	MTH 16-Apr-2010 HRS 352.3 LDG 221		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30393 E2	REPLACEMENT OF EEC SUPPORT BRACKETS	CR9		CATEGORY 3	MTH 16-Apr-2010 HRS 352.3 LDG 221		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30400 R1 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6					A/R	
MOC :										
SB PW500-72-30400 R1 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6					A/R	
MOC :										
SB PW500-72-30400 R2 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6					A/R	
MOC :										
SB PW500-72-30400 R2 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6					A/R	
MOC :										
SB PW500-72-30400 R3 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6					-	
MOC :										
SB PW500-72-30400 R3 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6					-	
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30400 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30401 R1 E1	RE-PROGRAMMING/REPLACEMENT - MODIFICATION ELECTRONIC ENGINE CONTROL			CATEGORY 5			-			
	MOC :									
SB PW500-72-30401 R1 E2	RE-PROGRAMMING/REPLACEMENT - MODIFICATION ELECTRONIC ENGINE CONTROL			CATEGORY 5			-			
	MOC :									
SB PW500-72-30401 R2 E1	RE-PROGRAMMING REPLACEMENT- MODIFICATION ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30434 R5)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30401 R2 E2	RE-PROGRAMMING REPLACEMENT- MODIFICATION ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30434 R5)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30404 R3 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30404 R3 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30405 R1 E1	FUEL NOZZLE MANIFOLD - REPLACEMENT OF			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30405 R1 E2	FUEL NOZZLE MANIFOLD - REPLACEMENT OF			CATEGORY 6			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30405 R2 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R2 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R3 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R3 E2	REPLACEMENT OF - FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 E1	FUEL NOZZLE MANIFOLD - REPLACEMENT OF			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30405 E2	FUEL NOZZLE MANIFOLD - REPLACEMENT OF			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30411 R1 E1	REPLACEMENT OF GASKETS			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30411 R1 E2	REPLACEMENT OF GASKETS			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30411 E1	REPLACEMENT OF GASKETS			CATEGORY 8			A/R			
MOC :										
SB PW500-72-30411 E2	REPLACEMENT OF GASKETS			CATEGORY 8			A/R			
MOC :										
SB PW500-72-30413 R1 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 R1 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 R2 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 R2 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30413 R3 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 R3 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 R4 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 R4 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 R5 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
MOC :										
SB PW500-72-30413 R5 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
MOC :										
SB PW500-72-30413 R6 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
MOC :										
SB PW500-72-30413 R6 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
MOC :										
SB PW500-72-30413 R7 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
MOC :										
SB PW500-72-30413 R7 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
MOC :										
SB PW500-72-30413 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30415 R1 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30415 R1 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30415 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30416 R1 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
MOC :										
SB PW500-72-30416 R1 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
MOC :										
SB PW500-72-30416 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			RECOMMENDED			A/R			
MOC :										
SB PW500-72-30416 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			RECOMMENDED			A/R			
MOC :										
SB PW500-72-30417 R1 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R1 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R2 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R2 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R3 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R3 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R4 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30417 R4 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R5 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R5 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R6 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R6 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R7 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30417 R7 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30417 R8 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 10			-			
MOC :										
SB PW500-72-30417 R8 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 10			-			
MOC :										
SB PW500-72-30417 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30418 R1 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30418 R1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			A/R			
E2	MOC :									
SB PW500-72-30418 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			A/R			
E2	MOC :									
SB PW500-72-30418 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			A/R			
E1	MOC :									
SB PW500-72-30419 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30419 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30420 R1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30420 R1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30420 R2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30420 R2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30420 R3	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE	KICT		CATEGORY 3	MTH 28-Jan-2014 HRS 856		-			Complete
E1	MOC :									
	COMPLIED WITH - REMOVED NO. 1 ENGINE - COMPRESSOR BLEED SERVO VALVE PER P&WC S.B. NO PW500-72-30420 R3, P/N: 30J3052-01, S/N: TR0175, AND INSTALLED A NEW SERVO VALVE IAW PRATT & WHITNEY CANADA 545C ENGINE M/M CHAPTER 75-30-01.									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30420 R3	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE									
E2		KICT		CATEGORY 3	MTH 28-Jan-2014 HRS 856 LDG 523	-				Complete
	MOC : COMPLIED WITH - ACCOMPLISHED TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30420 R3, DATED MARCH 14, 2013 (P&WC S.B. NO. PW500-72-30420 R3) INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-REPLACEMENT/MODIFICATION OF.									
SB PW500-72-30420 R4	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE									
E1				CATEGORY 3		-				
	MOC :									
SB PW500-72-30420 R4	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE									
E2				CATEGORY 3		-				
	MOC :									
SB PW500-72-30420 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE									
E1				CATEGORY 6		-				N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1									
SB PW500-72-30420 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE									
E2				CATEGORY 6		-				N/A
	MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1									
SB PW500-72-30423 R1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY									
E1				CATEGORY 6		-				
	MOC :									
SB PW500-72-30423 R1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY									
E2				CATEGORY 6		-				
	MOC :									
SB PW500-72-30423 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY									
E1				CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30423 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY									
E2				CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30425 R1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL									
E1				CATEGORY 3			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30425 R1 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			SEAL CATEGORY 3			A/R			
MOC :										
SB PW500-72-30425 R2 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						A/R			
MOC :										
SB PW500-72-30425 R2 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						A/R			
MOC :										
SB PW500-72-30425 R3 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						-			
MOC :										
SB PW500-72-30425 R3 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						-			
MOC :										
SB PW500-72-30425 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						A/R			
MOC :										
SB PW500-72-30425 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						A/R			
MOC :										
SB PW500-72-30426 E1	FAN CASE ASSEMBLY - REPLACEMENT OF						A/R			
MOC :										
SB PW500-72-30426 E2	FAN CASE ASSEMBLY - REPLACEMENT OF						A/R			
MOC :										
SB PW500-72-30427 R1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY						-			
MOC :										
E1										
MOC :										
SB PW500-72-30427 R1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY						-			
MOC :										
E2										
MOC :										
SB PW500-72-30427 R2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY						-			
MOC :										
E1										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30427 R2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30427 R3	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30427 R3	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30427 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			A/R			
E1	MOC :									
SB PW500-72-30427 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			A/R			
E2	MOC :									
SB PW500-72-30428 R1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			A/R			
E1	MOC :									
SB PW500-72-30428 R1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			A/R			
E2	MOC :									
SB PW500-72-30428 R2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30428 R2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30428 R3	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30428 R3	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30428 R4	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
E1	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30428 R4 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
MOC :										
SB PW500-72-30428 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30428 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R1 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R1 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R2 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R2 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R3 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R3 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30432 R1 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										
SB PW500-72-30432 R1 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										
SB PW500-72-30432 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										
SB PW500-72-30432 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF CATEGORY 7						A/R			
MOC :										
SB PW500-72-30434 R1 E1	ELECTRONIC ENGINE CONTROL / REPLACEMENT-MODIFICATION	KLUK		CATEGORY 3	MTH 24-Feb-2011 HRS 535.7 LDG 336		A/R			N/A
MOC : NOT APPLICABLE - N/A BY ENGINE S/N.										
SB PW500-72-30434 R1 E2	ELECTRONIC ENGINE CONTROL / REPLACEMENT-MODIFICATION	KLUK		CATEGORY 3	MTH 24-Feb-2011 HRS 535.7 LDG 336		A/R			N/A
MOC : NOT APPLICABLE - N/A BY ENGINE S/N.										
SB PW500-72-30434 R2 E1	ELECTRONIC ENGINE CONTROL / REPLACEMENT-MODIFICATION			CATEGORY 3			-			
MOC :										
SB PW500-72-30434 R2 E2	ELECTRONIC ENGINE CONTROL / REPLACEMENT-MODIFICATION			CATEGORY 3			-			
MOC :										
SB PW500-72-30434 R3 E1	REPLACEMENT-MODIFICATION - ELECTRONIC ENGINE CONTROL			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30434 R3 E2	REPLACEMENT-MODIFICATION - ELECTRONIC ENGINE CONTROL			CATEGORY 3	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30434 R4	REPLACEMENT-MODIFICATION ELECTRONIC ENGINE CONTROL	MCO		CATEGORY 3	MTH 03-May-2013 HRS 724.3 LDG 446	-				Complete
E1	MOC : COMPLIED WITH									
SB PW500-72-30434 R4	REPLACEMENT-MODIFICATION ELECTRONIC ENGINE CONTROL	MCO		CATEGORY 3	MTH 03-May-2013 HRS 724.3 LDG 446	-				Complete
E2	MOC : COMPLIED WITH									
SB PW500-72-30434 R5	REPLACEMENT - MODIFICATION OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30478 R3)			CATEGORY 10		-				
E1	MOC :									
SB PW500-72-30434 R5	REPLACEMENT - MODIFICATION OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30478 R3)			CATEGORY 10		-				
E2	MOC :									
SB PW500-72-30436 R1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7		-				
E1	MOC :									
SB PW500-72-30436 R1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7		-				
E2	MOC :									
SB PW500-72-30436 R2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7		-				
E1	MOC :									
SB PW500-72-30436 R2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7		-				
E2	MOC :									
SB PW500-72-30436 R3	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7		-				
E1	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30436 R3	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30436 E1	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF									
				CATEGORY 7			A/R			
E2	MOC :									
SB PW500-72-30436 E2	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF									
				CATEGORY 7			A/R			
E2	MOC :									
SB PW500-72-30438 R5	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R3)									
				CATEGORY 10						
E1	MOC :									
SB PW500-72-30438 R5	REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R3)									
				CATEGORY 10						
E2	MOC :									
SB PW500-72-30440 R1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									
				CATEGORY 6			A/R			
E1	MOC :									
SB PW500-72-30440 R1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									
				CATEGORY 6			A/R			
E2	MOC :									
SB PW500-72-30440 R2	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									
				CATEGORY 6			A/R			
E1	MOC :									
SB PW500-72-30440 R2	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									
				CATEGORY 6			A/R			
E2	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30440 R3	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30440 R3	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30440 R4	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30440 R4	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30440 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			A/R			
E1	MOC :									
SB PW500-72-30440 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			A/R			
E2	MOC :									
SB PW500-72-30445 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			A/R			
E1	MOC :									
SB PW500-72-30445 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			A/R			
E2	MOC :									
SB PW500-72-30446 R1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
E1	MOC :									
SB PW500-72-30446 R1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
E2	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30446 R2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY									
				CATEGORY 7						
E1	MOC :									
SB PW500-72-30446 R2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30447 R1	NEW COATING MODIFICATION OF GAS GENERATOR CASE									
E1				CATEGORY 6						
	MOC :									
SB PW500-72-30447 R1	NEW COATING MODIFICATION OF GAS GENERATOR CASE									
E2				CATEGORY 6						
	MOC :									
SB PW500-72-30447 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE									
				CATEGORY 6						
	MOC :									
SB PW500-72-30447 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE									
				CATEGORY 6						
	MOC :									
SB PW500-72-30449 R1	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF									
				CATEGORY 7						
E1	MOC :									
SB PW500-72-30449 R1	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30449 R2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY									
E1				CATEGORY 7						
	MOC :									
SB PW500-72-30449 R2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY									
E2				CATEGORY 7						
	MOC :									
SB PW500-72-30449 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY									
				CATEGORY 7						A/R
	MOC :									
SB PW500-72-30449 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY									
				CATEGORY 7						A/R
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30453 R1 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 R1 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30463 R1 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30463 R1 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL	KICT		CATEGORY 7	MTH 28-Jan-2014 HRS 856 LDG 523		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30463 R1, DATED NOVEMBER 20, 2012 (P&WC S.B. NO. PW500-72-30463 R1) REPLACEMENT OF ACCESSORY DRIVE LIP SEAL - REPLACEMENT OF										
SB PW500-72-30463 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30463 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30465 R1 E1	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
MOC :										
SB PW500-72-30465 R1 E2	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
MOC :										
SB PW500-72-30465 E1	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
MOC :										
SB PW500-72-30465 E2	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
MOC :										
SB PW500-72-30466 E1	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY			CATEGORY 7			-			
MOC :										
SB PW500-72-30466 E2	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30470 R1 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30470 R1 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30470 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30470 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30474 R1 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30474 R1 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30474 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS			OPTIONAL			-			
	MOC :									
SB PW500-72-30474 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS			OPTIONAL			-			
	MOC :									
SB PW500-72-30475 PART A E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 PART A E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 PART B E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 PART B E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30475 R1 PART A	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7						

E1

MOC :

SB PW500-72-30475 R1 PART A	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7						
--------------------------------	---	--	--	------------	--	--	--	--	--	--

E2

MOC :

SB PW500-72-30475 R1 PART B	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7						
--------------------------------	--	--	--	------------	--	--	--	--	--	--

E1

MOC :

SB PW500-72-30475 R1 PART B	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7						
--------------------------------	--	--	--	------------	--	--	--	--	--	--

E2

MOC :

SB PW500-72-30475 R1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7						
-------------------------	--	--	--	------------	--	--	--	--	--	--

E1

MOC :

SB PW500-72-30475 R1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7						
-------------------------	--	--	--	------------	--	--	--	--	--	--

E2

MOC :

SB PW500-72-30475 R2 PART A	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7						
--------------------------------	---	--	--	------------	--	--	--	--	--	--

E1

MOC :

SB PW500-72-30475 R2 PART A	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7						
--------------------------------	---	--	--	------------	--	--	--	--	--	--

E2

MOC :

SB PW500-72-30475 R2 PART B	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7						
--------------------------------	--	--	--	------------	--	--	--	--	--	--

E1

MOC :



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30475 R2 PART B	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7						
E2	MOC :									
SB PW500-72-30475 R2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7						
E1	MOC :									
SB PW500-72-30475 R2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7						
E2	MOC :									
SB PW500-72-30475 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7						
E1	MOC :									
SB PW500-72-30475 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7						
E2	MOC :									
SB PW500-72-30478 R1	REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 5						
E1	MOC :									
SB PW500-72-30478 R1	REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 5						
E2	MOC :									
SB PW500-72-30478 R2	REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 5						
E1	MOC :									
SB PW500-72-30478 R2	REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 5						
E2	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30478 R3	REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 3			-			
E1	MOC :									
SB PW500-72-30478 R3	REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 3			-			
E2	MOC :									
SB PW500-72-30478 R4	REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 3	MTH		24		01-Dec-2017	New Req
E1	MOC :									
SB PW500-72-30478 R4	REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 3	MTH		24		01-Dec-2017	New Req
E2	MOC :									
SB PW500-72-30478 E1	REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 5			-			
E1	MOC :									
SB PW500-72-30478 E2	REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 5			-			
E2	MOC :									
SB PW500-72-30479 R1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5			-			
E1	MOC :									
SB PW500-72-30479 R1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5			-			
E2	MOC :									
SB PW500-72-30479 R2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5			-			
E1	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30479 R2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THEOIL TRANSFER TUBE			CATEGORY 5			-			
E2	MOC :									
SB PW500-72-30479 R3	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THEOIL TRANSFER TUBE			CATEGORY 5			-			
E1	MOC :									
SB PW500-72-30479 R3	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THEOIL TRANSFER TUBE			CATEGORY 5			-			
E2	MOC :									
SB PW500-72-30479 R3	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30479 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30480 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS			CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30480 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS			CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30481 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE			CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30481 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE			CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30482 R1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
E1	MOC :									
SB PW500-72-30482 R1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
E2	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30482 R2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT									
				CATEGORY 3			-			
E1	MOC :									
SB PW500-72-30482 R2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT									
				CATEGORY 3			-			
E2	MOC :									
SB PW500-72-30482 R3	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)									
				CATEGORY 10			-			
E1	MOC :									
SB PW500-72-30482 R3	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)									
				CATEGORY 10			-			
E2	MOC :									
SB PW500-72-30482 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT									
				CATEGORY 3			-			
E1	MOC :									
SB PW500-72-30482 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT									
				CATEGORY 3			-			
E2	MOC :									
SB PW500-72-30483 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30483 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30483 R2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7			-			
E1	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30483 R2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30483 R3	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)									
				CATEGORY 10						
E1	MOC :									
SB PW500-72-30483 R3	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)									
				CATEGORY 10						
E2	MOC :									
SB PW500-72-30483 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E1	MOC :									
SB PW500-72-30483 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30485 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE									
				CATEGORY 7						
E1	MOC :									
SB PW500-72-30485 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30487 R3	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)									
				CATEGORY 10						
E1	MOC :									
SB PW500-72-30487 R3	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)									
				CATEGORY 10						
E2	MOC :									
SB PW500-72-30491 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E1	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30491 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30491 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E1	MOC :									
SB PW500-72-30491 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30492 R1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER									
				CATEGORY 7						
E1	MOC :									
SB PW500-72-30492 R1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER									
				CATEGORY 7						
E2	MOC :									
SB PW500-72-30492 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER									
E1	MOC :									
SB PW500-72-30492 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER									
E2	MOC :									
SB PW500-72-30492 R3	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER									
				CATEGORY 6						
E1	MOC :									
SB PW500-72-30492 R3	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER									
				CATEGORY 6						
E2	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30492 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER			CATEGORY 7						
	MOC :									
SB PW500-72-30492 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER			CATEGORY 7						
	MOC :									
SB PW500-72-30495 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498)			CATEGORY 10						
	MOC :									
SB PW500-72-30495 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498)			CATEGORY 10						
	MOC :									
SB PW500-72-30496 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 6						
	MOC :									
SB PW500-72-30496 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 6						
	MOC :									
SB PW500-72-30498 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7						
	MOC :									
SB PW500-72-30498 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7						
	MOC :									
SB PW500-72-30502 R1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7						
E1										
	MOC :									
SB PW500-72-30502 R1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7						
E2										
	MOC :									
SB PW500-72-30502 R2 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7						
	MOC :									
SB PW500-72-30502 R2 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30502 R2 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R2 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30505 R1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
	MOC :									
SB PW500-72-30505 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30505 R2 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			GASKETS CATEGORY 3	MTH HRS		DUE DUE DUE		31-Jan-2015 1456	-10 m 4 d 341.6
Over Due										
MOC :										
SB PW500-72-30505 R2 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			GASKETS CATEGORY 3	MTH HRS		DUE DUE DUE		31-Jan-2015 1456	-10 m 4 d 341.6
Over Due										
MOC :										
SB PW500-72-30505 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			GASKETS CATEGORY 3			-			
MOC :										
SB PW500-72-30505 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			GASKETS CATEGORY 3			-			
MOC :										
SB PW500-72-30506 R1 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R1 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R2 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R2 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R1 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R1 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30508 R2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS									
				CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30508 R2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS									
				CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30508 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS									
				CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30508 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS									
				CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30510 E1	REPLACEMENT OF PRIMARY AND SECONDARY FUEL TUBE SUPPORT BRACKET									
				CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30510 E2	REPLACEMENT OF PRIMARY AND SECONDARY FUEL TUBE SUPPORT BRACKET									
				CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30511 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS									
				CATEGORY 6			-			
E1	MOC :									
SB PW500-72-30511 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS									
				CATEGORY 6			-			
E2	MOC :									
SB PW500-72-30516 R1	REPLACEMENT OF HP TURBINE SEAL RINGS									
				CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30516 R1	REPLACEMENT OF HP TURBINE SEAL RINGS									
				CATEGORY 7			-			
E2	MOC :									
SB PW500-72-30516 R2	REPLACEMENT OF HP TURBINE SEAL RINGS									
				CATEGORY 7			-			
E1	MOC :									
SB PW500-72-30516 R2	REPLACEMENT OF HP TURBINE SEAL RINGS									
				CATEGORY 7			-			
E2	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30517 E1	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30517 E2	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30523 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72-30523 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72-30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									
ASB PW500-72-A30452 R1	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3	MTH		-			
	MOC :									
ASB PW500-72-A30452 R1	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3	MTH		-			
	MOC :									
ASB PW500-72-A30452 R2	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
	MOC :									
ASB PW500-72-A30452 R2	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
	MOC :									
ASB PW500-72-A30452	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3			-			
	MOC :									
ASB PW500-72-A30452	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-76-04	ENGINE CONTROLS - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN 30434 TURBOFAN ENGINE - ELECTRONIC ENGINE CONTROL/REPLACEMENT-MODIFICATION AND P&WC SERVICE BULLETIN 30438 TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC) -REPLACEMENT/MODIFICATIONS OF	MCO		RECOMMENDED	MTH		A/R			
MOC :										
SL 560XL-76-03 R1	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30438, REPLACEMENT/MODIFICATIONS OF TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC)	MCO		RECOMMENDED	MTH 03-Dec-2011 HRS 567.2 LDG 356		A/R			N/A
MOC : NOT APPLICABLE - SL560XL-76-03 R1 & P&WC SB500-72-30438 DOES NOT APPLY TO EEC INSTALLED PN.1012400-1-003										
SL 560XL-76-03 R2	ENGINE CONTROLS - TRANSMITTAL OF PRATT & WHITNEY SERVICE BULLETIN 30438 TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT / MODIFICATIONS OF AND SERVICE BULLETIN 30478 TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT / FIELD MODIFICATION OF			RECOMMENDED	MTH HRS		300		1417.25	302.85
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1974-08-09 R3	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	KICT		MANDATORY	MTH 28-Jan-2014 HRS 856 LDG 523		1000		1856	741.6 Complete
MOC : COMPLIED WITH - ACCOMPLISHED AD1974-08-09 R3; WASTER RECEPTACLE INSPECTION, DATED MARCH 28, 2012										
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS	CR9		MANDATORY	MTH 16-Apr-2010 HRS 352.3 LDG 216		A/R			N/A
MOC : NOT APPLICABLE - N/A DUE TO MANUFACTURE										
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI	CR9		MANDATORY	MTH 16-Apr-2010 HRS 352.3 LDG 216		A/R			N/A
MOC : NOT APPLICABLE - N/A DUE TO MANUFACTURE										
FAA 2012-09-01	LANDING GEAR - TORQUE LUG - INSPECTION	MCO		MANDATORY	MTH 07-May-2012 HRS 576 LDG 364		-			Complete
MOC : COMPLIED WITH										
AD 34-26	HONEYWELL FMS W/NZ2000	MCO			MTH 02-Jun-2009 HRS 87		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)			MANDATORY	DAYS		30		10-Jul-2015	-4 m 24 d Over Due
MOC :										
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD			MANDATORY	MTH		6		10-Dec-2015	6 d
MOC :										
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT			MANDATORY			-			
MOC :										
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD			MANDATORY			-			
MOC :										
EASA 2015-0093	APPLIANCE AD - NAVIGATION ATTITUDE HEADING REFERENCE SYSTEM MODIFICATION / REPLACEMENT			MANDATORY			-			
MOC :										
FAA 2001-23-17 34AD-09 : XL	APPLIANCE AD - GARMIN INTERNATIONAL GNS 430	ICT		MANDATORY	MTH 21-Jan-2009 HRS 7		A/R			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2006-22-05 <i>34AD-15 : XL</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM MANDATORY	ICT			MTH 21-Jan-2009 HRS 7		A/R			N/A
MOC : NOT APPLICABLE										
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	MCO		MANDATORY	MTH 08-Dec-2010 HRS 507.7 LDG 318		A/R			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2010-07-02 BY VISUAL INSPECTION. AD DOES NOT APPLY DUE AIRCRAFT BEING EQUIPPED WITH ROCKWELL COLLINS SYSTEM. NO FURTHER ACTION REQUIRED. PLEASE UPDATE CESCOM.										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	SBJD		MANDATORY	MTH 21-Dec-2012 HRS 690 LDG 421		-			N/A
MOC : NOT APPLICABLE - ON THE COMPONENT INSTALLED ON THE AIRCRAFT. INSTALLED TCAS MODEL TTR-400 P/N 822-1291-002 MANUFACTURED BY COLLINS. FOR MORE DETAILS SEE FCDA.										
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		24		14-Oct-2016	10 m 10 d
MOC :										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS			MANDATORY			-			
MOC :										
EASA 2014-0142 (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445952 WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS			MANDATORY	MTH		-			
MOC :										
EASA 2014-0142 (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD			MANDATORY			-			
MOC :										
EASA 2014-0142 (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD.			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
EASA 2014-0142 R1 (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS			MANDATORY	MTH		24		18-Jun-2016	6 m 14 d
MOC :										
EASA 2014-0142 R1 (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD			MANDATORY			-			
MOC :										
EASA 2014-0142 R1 (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD			MANDATORY			-			
MOC :										
EASA 2014-0142 R1	APPLIANCE AD - OXYGEN OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE IDENTIFICATION / REPLACEMENT			MANDATORY			-			
MOC :										
EASA 2014-0142	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT			MANDATORY			-			
MOC :										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER			MANDATORY	DAYS		30		27-Jan-2016	New Req
MOC :										
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).			MANDATORY	DAYS		30		27-Jan-2016	New Req
MOC :										
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1			MANDATORY	DAYS		30		27-Jan-2016	New Req
MOC :										
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."			MANDATORY	DAYS		30		27-Jan-2016	New Req
MOC :										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT			MANDATORY	MTH		12		28-Dec-2016	New Req
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**
 Aircraft Model: **560XLS+CITATION XLS+ (MSG)**
 Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**
 Airworthiness: **21-Jan-2009**
 Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS			MANDATORY MTH			-			New Req
MOC :										
FAA 2012-06-01	MODIFY THE DRAIN INSTALLATION OF THE TAILCONE STINGER ON THE AFT CANTED BULKHEAD	MCO		MANDATORY MTH	07-May-2012		-			Complete
HRS 576 LDG 364										
MOC : COMPLIED WITH										
FAA 2010-18-09 PARA (E)(2)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	MCO		MANDATORY MTH	09-Dec-2010		-			N/A
HRS 507.7 LDG 322										
E1	MOC : NOT APPLICABLE - AD 2010-18-09, N/A DUE TO ENGINE MODEL.									
FAA 2010-18-09 PARA (E)(2)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	MCO		MANDATORY MTH	09-Dec-2010		-			N/A
HRS 507.7 LDG 322										
E2	MOC : NOT APPLICABLE									
FAA 2010-18-09 PARA (E)(3)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	MCO		MANDATORY MTH	09-Dec-2010		-			N/A
HRS 507.7 LDG 322										
E1	MOC : NOT APPLICABLE - AD 2010-18-09, N/A DUE TO ENGINE MODEL.									
FAA 2010-18-09 PARA (E)(3)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	MCO		MANDATORY MTH	09-Dec-2010		-			N/A
HRS 507.7 LDG 322										
E2	MOC : NOT APPLICABLE									
FAA 2010-18-09 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	MCO		MANDATORY MTH	09-Dec-2010		-			N/A
HRS 507.7 LDG 318										
MOC : NOT APPLICABLE - AD 2010-18-09, N/A DUE TO ENGINE MODEL.										
FAA 2010-18-09 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	MCO		MANDATORY MTH	09-Dec-2010		-			N/A
HRS 507.7 LDG 318										
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **DISTRIBUIDORA BRASILIA DE VEICULOS S.A. - DISBRA**

Aircraft Model: **560XLS+CITATION XLS+ (MSG)**

Aircraft Serial: **560XL-6012** Unit: **6012** Reg No: **PP-VYV**

Airworthiness: **21-Jan-2009**

Print Date: **04-Dec-2015 7:33AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1114.4	627	08-Oct-2015	.07
ENG 1	1114.4	622	08-Oct-2015	.07
ENG 2	1114.4	622	08-Oct-2015	.07
APU	331.3	330	08-Oct-2015	.43

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
23FO-03XL <i>23FO-03 : XL</i>	AXXESS II IRIDIUM VOICE DATA FACTORY OPTION			675U FO	MTH 21-Jan-2009		-			
24FO-01XL/N <i>24FO-01 : XL/N</i>	BATTERY: SEALED LEAD ACID FACTORY OPTION			186N FO	MTH 21-Jan-2009		-			
34FO-05XL <i>34FO-05 : XL</i>	MARK V EGPWS W/RAAS FACTORY OPTION			691L FO	MTH 21-Jan-2009		-			
34FO-07XL <i>34FO-07 : XL</i>	SECOND FMS-3000 FACTORY OPTION			686S FO	MTH 21-Jan-2009		-			
34FO-09XL <i>34FO-09 : XL</i>	HF 9031A W/SELCAL-COLLINS FACTORY OPTION			632P FO	MTH 21-Jan-2009		-			
73FO-01XL <i>73FO-01 : XL</i>	CHIP DETECTOR: ENGINE FACTORY OPTION			10M FO	MTH 21-Jan-2009		-			