



# CESCOM 20 - Projected Maintenance Due

Owner: **TRADEWINDS AIRCRAFT SALES INC**

Aircraft Model: **525 - CJ1**

Aircraft Serial: **525-0538** Unit: **0538** Reg No: **N525AM**

Airworthiness: **22-Sep-2004**

Print Date: **01-Nov-2011 3:25PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
<b>AIRCRAFT</b>	<b>1106</b>	<b>898</b>	<b>31-Oct-2011</b>	<b>0.38</b>	<b>.28</b>	<b>45</b>	<b>41</b>	<b>120</b>	<b>3</b>
<b>ENG 1</b>	<b>1106</b>	<b>898</b>	<b>31-Oct-2011</b>	<b>0.38</b>	<b>.28</b>	<b>45</b>	<b>41</b>	<b>120</b>	<b>3</b>
<b>ENG 2</b>	<b>1106</b>	<b>898</b>	<b>31-Oct-2011</b>	<b>0.38</b>	<b>.28</b>	<b>45</b>	<b>41</b>	<b>120</b>	<b>3</b>
<b>AIR COND</b>	<b>440.9</b>		<b>31-Oct-2011</b>	<b>0.69</b>	<b>.9</b>	<b>82</b>		<b>120</b>	<b>3</b>

**\*\* Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

## New Requirements/Action Items

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SL 525-31-06	TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001							
			MTH 16-Apr-2010		12 MTH		31-Aug-2012	New Req
		MANDATORY	HRS 934		500 HRS		1583	
SL 525-35-06	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240							
			MTH 16-Apr-2010		1200 HRS		31-May-2013	New Req
		MANDATORY	HRS 934				2283.58	

## Overdue Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
051201 E1 <i>051200A : E1**L</i>	FJ44 CHECK 1	TUL	MTH 16-Apr-2010 HRS 934 LDG 697		150		1084	-22 <b>Over Due</b>
051201 E2 <i>051200A : E2**R</i>	FJ44 CHECK 1	TUL	MTH 16-Apr-2010 HRS 934 LDG 697		150		1084	-22 <b>Over Due</b>
5-12-10 <i>0512010</i>	INSPECTION DOCUMENT 10	ICT	MTH 03-Oct-2008 HRS 774		36 1200		31-Oct-2011 1974	-1 d 868 <b>Over Due</b>
5-12-11 <i>0512011</i>	INSPECTION DOCUMENT 11	ICT	MTH 03-Oct-2008 HRS 774		36 1200		31-Oct-2011 1974	-1 d 868 <b>Over Due</b>

## Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
5-12-12 <i>0512012</i>	INSPECTION DOCUMENT 12	MCO	MTH 22-Nov-2010 HRS 1000.8 LDG 778		12		30-Nov-2011	29 d
A243301 <i>0512009B : GILL</i>	FUNCTIONAL CHECK MAIN BATTERY LEAD ACID BATTERY (CAPACITY CHECK): INSPECTION DOCUMENT 09	KDAL	7638-44 MTH 08-Jun-2011 G02492945 HRS 1050.3 LDG 846		6 400		31-Dec-2011 1450.3	1 m 30 d 344.3
A361002 LEFT <i>0512022 : L</i>	DETAILED INSPECTION B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22	MCO	8161-1 MTH 14-Apr-2009 S4883T1134 HRS 835		300		1135	29
A361002 RIGHT <i>0512022 : R</i>	DETAILED INSPECTION B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22	MCO	8161-1 MTH 14-Apr-2009 S4883T1132 HRS 835		300		1135	29

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB 525-27-19 R1	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION							
			MTH 16-Apr-2010		36 MTH		13-Sep-2013	22 m 12 d
		MANDATORY	HRS 934		1200 HRS		2188.03	1082.03

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



## CESCOM 20 - Projected Maintenance Due

Owner: **TRADEWINDS AIRCRAFT SALES INC**

Aircraft Model: **525 - CJ1**

Aircraft Serial: **525-0538** Unit: **0538** Reg No: **N525AM**

Airworthiness: **22-Sep-2004**

Print Date: **01-Nov-2011 3:25PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
<b>AIRCRAFT</b>	<b>1106</b>	<b>898</b>	<b>31-Oct-2011</b>	<b>0.38</b>	<b>.28</b>	<b>45</b>	<b>41</b>	<b>120</b>	<b>3</b>
<b>ENG 1</b>	<b>1106</b>	<b>898</b>	<b>31-Oct-2011</b>	<b>0.38</b>	<b>.28</b>	<b>45</b>	<b>41</b>	<b>120</b>	<b>3</b>
<b>ENG 2</b>	<b>1106</b>	<b>898</b>	<b>31-Oct-2011</b>	<b>0.38</b>	<b>.28</b>	<b>45</b>	<b>41</b>	<b>120</b>	<b>3</b>
<b>AIR COND</b>	<b>440.9</b>		<b>31-Oct-2011</b>	<b>0.69</b>	<b>.9</b>	<b>82</b>		<b>120</b>	<b>3</b>

**\*\* Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

### Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB FJ44-72-066 R3 E1	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE		HRS MSC				1750	644
		RECOMMENDED			DUE			
SB FJ44-72-066 R3 E2	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE		HRS MSC				1750	644
		RECOMMENDED			DUE			
SB FJ44-72-076 E1	REWORK - ENGINE- COMPRESSOR STATOR		HRS MSC				3500	2394
		OPTIONAL			DUE			
SB FJ44-72-076 E2	REWORK - ENGINE- COMPRESSOR STATOR		HRS MSC				3500	2394
		OPTIONAL			DUE			
SB FJ44-72-087 R4 E1	ENGINE - BLEED VALVE SHAFT - REPLACE		HRS MSC				3500	2394
		OPTIONAL			-			
SB FJ44-72-087 R4 E2	ENGINE - BLEED VALVE SHAFT - REPLACE		HRS MSC				3500	2394
		OPTIONAL			-			